UNCLASSIFIED

8769




HEDIOLET SURVEY SERVEY AND INVERTORY

erres for the little length of the

Reproduced by
NATIONAL TECHNICAL
INFORMATION SERVICE
Springfield, Va. 22151



# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.




MEDICAL CAPABILITY SURVEY AND INVENTORY
OF THE
SHIPS OF THE AMPHIBIOUS FORCE
U. S. ATLANTIC FLEET

October 1970


Authors:
Franklin C. Broadwell
Raymond J. Mataloni
Francis B. Merkle

Prepared Under: Office of Naval Research Contract N00014-70-C-0284 Project NR-259-084

For and with the support of the Bureau of Medicine and Surgery



Distribution of this report is unlimited.



#### TABLE OF CONTENTS

#### SECTION I

#### INTRODUCTION

- Purpose of the Ship Medical Capability Inventory Data Collection Procedure 1.1
- 1.2
- 1.3 Method of Report Presentation
- Ships Surveyed 1.4

- 1.5 Consistency of Data
  1.6 Limitations on Report
  1.7 Major Medical Space Overviews

#### SECTION II

#### INDIVIDUAL SHIP MEDICAL CAPABILITY REPORT

NOTE: Individual ship booklets are provided for those ships listed in 1.4.

#### SECTION III

#### MEDICAL CAPABILITY SUMMARY

- 3.1
- Facility Summary Medical Capability Qualitative Analysis Medical Care Quantitative Analysis 3.2

#### SECTION I

#### INTRODUCTION

- 1.1 Purpose of the Ship Medical Capability Inventory
- 1.1.1 To provide a current inventory of the medical assets of the Amphibious Force, U. S. Atlantic Fleet.
- 1.1.2 To present the information essential to the evaluation of the ships' medical facilities, the selection of those suitable to act as casualty receiving ships and the determination of their capacities in that role.
- 1.1.3 To provide surgical team personnel with current medical capability reference material regarding the ships to which they may be assigned.
- 1.1.4 To focus attention on deficiencies which may be identified so that remedial action may be taken.
- 1.2 Data Collection Procedure
- 1.2.1 Ship Medical Capability Questionnaire
  - A questionnaire was prepared with a view toward identifying:
    - •• Medical facilities and equipment of individual ships
    - Quantitative and qualitative medical care which could be provided within the resources of each ship
    - Casualty flow onto and within individual ships
    - •• Ability of individual ships to support a Surgical Team and/or a Surgical Support Team
  - The questionnaire was tested by use in conjunction with visits to the USS GUAM (LPH-9), USS CHARLESTON (LKA-113), USS FRANCIS MARION (LPS-249) and the USS NEWPORT (LST-1179). Deficiencies noted in the questionnaire were corrected.
  - A revised questionnaire was then sent to each of the ships of the Amphibious Force, Atlantic Fleet (minus those pending decommissioning) for completion by cognizant, on-board medical personnel.

#### 1.2.2 Ship Medical Capability Inspection

An on-board inspection of medical facilities and equipment of all available ships in the Norfolk area was conducted by contract personnel to verify and supplement data incorporated in the completed questionnaire. Of the forty-five ships involved, sixteen were inspected (one of which was under construction), twelve were deployed, five were in process of being built and twelve were scheduled to be decommissioned.

#### 1.3 Method of Report Presentation

- This report consists of three sections, the introduction, the reports of individual ship's medical capability and a medical capability summary. The individual ship medical capability portion, Section II, is designed so that it may be divided into individual ship medical capability booklets.
- The information presented in this report is based upon that provided by the ships in response to the question-naires. When feasible, amplifying information was obtained by visits to the ships, as stated in paragraph 1.2.2. The deficiencies and comments noted are those considered important by the medical personnel of the ships concerned.

#### 1.4 Ships Surveyed

Figure 1-1, Ship Medical Capability Survey Method and Remarks lists the ships of the Amphibious Force, U. S. Atlantic Fleet. It identifies the method by which the survey was conducted and provides appropriate remarks plus the identification code of the authorized medical allowance for each ship.

#### 1.5 Consistency of Data

The process of summarizing the data contained in the questionnaires disclosed a number of cases of apparent inconsistency. Some appeared to be the result of differences among ships of the same class, whereas others might be attributed to errors in recording data. To the extent feasible, such inconsistencies were corrected by comparisons among sister ships, by reference to the available drawings, etc. The tabulation of compartment numbers shown in Figure 1-2, Data Sample, derived from the questionnaires from four supposedly similar ships, is an example of apparent inconsistency.

#### 1.6 Limitations on Report

This report is not a complete report of the total medical capability of the ships of the Amphibious Force, U. S. Atlantic Fleet, owing primarily to the short time available and to the fact that a number of ships were deployed. These two factors combined to limit the number of ships which could be visited. In order to permit the insertion of additional information as it becomes available in the future, tabs for all ships receiving questionnaires are included in the initial submission of the report. The loose-leaf binding employed will facilitate such future additions.

#### 1.7 Major Medical Space Overviews

In the cases of those ships in which it was practicable and profitable, major medical space overviews (composite layouts of the medical spaces) have been provided to show the major medical spaces.

	SHIP	SURVEY METHOD	НОВ		AUTH, MEDICAL
TYPE-HULL	NAME	<b>⊢</b>	VISIT	KEMAKNS	ALLOW. CODE
LCC-18	USS POCONO	No.	No	Decommissioned	
LCC-20	USS MOUNT WHITNEY	Yes	10/22/70	In this report	812
LPH-7	USS GUADALCANAL	Yes	10/13/70	In this report	842
LPH-9	USS GUAM	Yes	0.V.	In this report	842
LPH-12	USS INCHON	Yes	No	In this report	842
LPD-1	USS RALEIGH	Yes	0 N.	In this report	793
LPD-3	USS LA SALLE	Yes	10/13/70	In this report	793
LPD-4	USS AUSTIN	Yes	10/13/70	In this report	793
LPD-11	USS CORONADO	Yes	10/22/70	In this report	793
LPD-13	USS NASHVILLE	Yes	10/13/70	In this report	793
LSD-14	USS RUSHMORE	No	ON	Decommissioned	
LSD-20	USS DONNER	ON	No	Decommissioned	
LSD-21	USS FORT MANDAN	Yes	ON	In this report	753
LSD-25	USS SAN MARCOS	Yes	No	In this report	753
LSD-29	USS PLYMOUTH ROCK	Yes	10/12/70	In this report	753
LSD-30	USS FORT SNELLING	Yes	10/13/70	In this report	753
LSD-32	USS SPIEGEL GROVE	Yes	10/12/70	In this report	753
LSD-34	USS HERMITAGE	Yes	10/12/70	In this report	753
LSD-37	USS PORTLAND	Yes	No	In this report	753
LSD-38	USS PENSACOLA	Yes	No	Being built	753
LPA-36	USS CAMBRIA	No	No	Decommissioned	
LPA-38	USS CHILTON	Yes	10/13/70	In this report	830
LPA-249	USS FRANCIS MARION	Yes	No	In this report	830
			] ;		

Figure 1-1, Ship Medical Capability Survey Method and Remarks

	SHIP	SURVEY METHOD	HOD		AUTH, MEDICAL
TYPE-HULL	NAME	QUESTIONNAIRE	VISIT	KEMAKKS	• 1
LKA-56	USS ARNEB	No	No	Decommissioned	
LKA-61	USS MULIPHEN	No	No	Decommissioned	
LKA-93	USS YANCEY	No	No	Decommissioned	
LKA-103	USS RANKIN	No	ON	Decommissioned	
LKA-107	USS VERMILLION	No	No	Decommissioned	
LKA-113	USS CHARLESTON	Yes	10/13/70	In this report	754
LKA-117	USS EL PASO	Yes	No	In this report	754
LST-1156	USS TERREBONNE PARISH	Yes	10/12/70	In this report	743
LST-1160	USS TRAVERSE COUNTY	No	No	Decommissioned	
LST-1162	USS WAHKIAKUM COUNTY	No	No	Decommissioned	
LST-1163	USS WALDO COUNTY	No	No	Decommissioned	
LST-1164	USS WALWORTH COUNTY	Yes	No	In this report	743
LST-1171	USS DESOTO COUNTY	Yes	ON	In this report	743
LST-1173	USS SUFFOLK COUNTY	Yes	No	In this report	743
LST-1174	USS GRANT COUNTY	Yes	10/12/70	In this report	743
LST-1175	USS YORK COUNTY	Yes	No	In this report	743
LST-1176	USS GRAHAM COUNTY	Yes	No	In this report	743
LST-1177	USS LORAIN COUNTY	Yes	10/12/70	In this report	743
LST-1178	USS WOOD COUNTY	Yes	No	In this report	743
LST-1179	USS NEWPORT	Yes	10/13/70	In this report	743
LST-1188	USS SAGINAW	Yes	No	Being built	743
LST-1190	USS BOULDER	Yes	No	Being built	743

Ship Medical Capability Survey Method and Remarks (continued) Figure 1-1,

Figure 1-2, Data Sample

## UNCLASSIFIED

INVENTORY OF
THE MEDICAL CAPABILITY
OF THE
USS MOUNT WHITNEY
LCC-20

## TABLE OF CONTENTS

<u>ltem</u>	Page N	<u>o .</u>
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Major Medical Space Overview	1 2	
Operating Room	4	
Operating Room (non-dedicated)	5	
Primary Ward	6	
Quiet Room	6 7	
Dental Operating Room #1	8	
Dental Operating Room #2	9	
Dental Dept. Office & Dental Supply	10	
Medical Administration	11	
Laboratory	12	
X-Ray (Fixed)	12	
Physiotherapy	12	
Pharmacy	12	
Central Supply/Sterilization Room	13	
Dental X-Ray (Fixed)	13	
Complement	14	
Status of Outstanding Shipalts	14	
Size and Location of Area for Breakout of Surgical Block	14	
Stowage Near Helo Pad for Replacement Litters and Blanket		

#### USS MOUNT WHITNEY

LCC - 20

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support to other ships(3) Medical support for embarked non-crew personnel

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area		Not established
Operating Room(s)	Main OR	
Non-Ded OR(s)	Surg. Dress Room	
Minor Surgery Room	Surg. Dress Room	Same as Non-Ded OR
Primary Ward	Ward	19 beds
Overflow Ward(s)		None
Quiet Room(s)		4 beds
Intensive Care Unit		None
X-Ray	Fixed Unit	300 ma
Physiotherapy		Wpool, Baker, I.R. light
Pharmacy		Standard
Blood Storage		Not determined
Morgue	Refrigerator	
Dental OR		2 complete OR's
Dental X-Ray	Fixed Unit	Not installed
Laboratory	Clinical Lab	Diagnostic tests
Admin. Office	Admin.	3 desks, 6 files
Supply Room		Not established
Battle Dressing	Main BDS same as	Only Main BDS estab-
Stations	Minor Surgery	lished to date

#### CASUALTY FLOW:

Not established - ship under construction. However, there is a 12' x 12' elevator which runs directly from helo pad to medical spaces which would be logical casualty flow route.

#### SIGNIFICANT DEFICIENCIES:

None reported - ship under construction.

### MAJOR MEDICAL SPACE OVERVIEW


REFERENCE:	LOCATION:	FACILITY:
1	3-119-6-Q	Dental Operating Room #2
2 3	3 - 115 - 2 - Q	Dental Department Office
3	3 - 1 1 2 - 6 - L	Passage
	3-113-2-Q	Dental X-Ray Room
5	3 - 112 - 8 - Q	Dental X-Ray Dark Room
5	3 - 109 - 8 - Q	Dental Operating Room #1
7		Storerooms
8	3 - 103 - 2 - Q	Medical Property and
		Accounting Office
9	3 - 119 - 4 - Q	Medical X-Ray Dark Room
10	3-119-2-Q	Medical X-Ray Room
11	3 - 112 - 2 - L	Ward
1.2	3 - 112 - 4 - Q	Utility Room
13	3 - 109 - 4 - L	Ward Bath
14	3 - 109 - 2 - L	Diet Pantry
15	3-108-0-L	Passage
16	3 - 104 - 4 - Q	Bacteriological Laboratory
17	3-106-2-L	int Room
18	3 - 104 - 2 - L	ς et Room Bath
19	3 - 104 <b>-</b> 0 - Q	Medical Records Office
20	3-109-1-L	Passage
21	3-119-1-Q	Pharmacy
22	3-115-1-Q	Operating Room
23	3-113-1-Q	Sterilizer Room
24	3-109-3-Q	Surgical Dressing Room and
		Main Battle Dressing
2.5	3-106-1-0	Station Modical Department Office
25	3-106-1-Q	Medical Department Office
26	3-104·1-Q	Consultation Room
27	3-109-6-L	Passage

(See Floor Plan, Page 3)

## MAJOR MEDICAL SPACE OVERVIEW

FLOOR PLAN: Not to scale

(See Reference, Page 2)



#### OFERATING ROOM

LOCATION: 3-115-1-Q

NORMAL USE: Main Operating Room

FLOOR PLAN: Not to scale


EQUIPMENT: 1-OR table

2-Cabinet & med locker

3-Instrument table 4-Instrument table

5-Surg. field light 6-Dressing table 7-X-ray film viewer

8-Castle lights



#### OPERATING ROOM (non-dedicated)

LOCATION: 3-109-3-Q


NORMAL USE: Surgical Dressing Room/Main BDS

FLOOR PLAN: Not to scale EQUIPMENT:

1-Cab & Tock-Type A
2-Patient exam tbl.
3-Refrig. T-1,S. 10
4-Instrument ster.
5-Sterilizer shelf
6-Examining chair
7-Instrument table
8-Chair-Style A
9-Chair-Style B
10-Antidote locker
11-X-ray viewer
12-Cab & lock-Type B
13-Book rack
14-Log desk

15-File cab & locker Type 1

16-Castle lights



#### PRIMARY WARD

LOCATION: 3-112-2-L

NORMAL USE: Ward

FLOOR PLAN: Not to scale

**EQUIPMENT:** 


1-19 beds

2-Bedside lockers

3-Cabinets

4-Linen locker

5-Instrument Sterilizer




## QUIET ROOM

LOCATION: 3-106-2-L

NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale

EQUIPMENT: 1-beds (2 high) 2-bedside locker




#### DENTAL OPERATING ROOM #1

LOCATION: 3-109-8-Q

NORMAL USE: Dental OR

FLOOR PLAN: Not to scale



#### **EQUIPMENT:**

1-Dent instr cab
2-Operating chair
3-Dent oper unit
4-Dent oper light
\*5-Amalgamator

\*6-Illuminator,X-ray 7-Surg sterilizer 8-Oral evacuator 9-Aspirator,suction

10-Desk 11-Chair 12-Hamper

13-Instrument stand 14-Surgical sink


\* Not shown on drawing

#### DENTAL OPERATING ROOM #2

LOCATION: 3-119-6-Q

NORMAL USE: Dental OR

FLOOR PLAN: Not to scale



#### EQUIPMENT:

1-Dent instr cab 2-Operating chair 3-Dent oper unit 4-Dent oper light

\*5-Amalgamator \*6-Illuminator, x-ray 7-Surg sterilizer 8-Oral evacuator 9-Aspirator, suction 10-Surgical Sink 11-Desk

12-Chair 13-Cabinet shelf

14-Hamper


\*Not shown on drawing

## DENTAL DEPARTMENT OFFICE & DENTAL SUPPLY

LOCATION: 3-115-2-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Cabinet 2-Card index 3-Chair 4-Desk



USS MOUNT WHITNEY


LCC - 20

#### MEDICAL ADMINISTRATION

LOCATION: 3-104-0-Q

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Letter file Type III
2-Legal file Type I
3-Legal file Type II
4-Visual index
5-Desk



#### LABORATORY

LOCATION: 3-104-4-Q

Routine diagnostic laboratory procedures. Wiblood storage capability not determined since CAPABILITY:

ship is still under construction.

MAJOR EQUIPMENT:

5-Incubator 1-Centrifuge

6-Variable speed rotator 2-Water bath 7-Binocular microscope 3-Shaker

4-Refrigerator

Other equipment may be installed when construction is NOTE:

complete.

#### X-RAY (Fixed)

LOCATION: 3-119-2-Q

MAJOR EQUIPMENT:

5-Film file cabinet 1-300 ma X-Ray unit 6-Dark room safelight 2-Film cassette transfer

7-Film dryer 3-Film holders

8-Developing tank 4-View box

#### PHYSIOTHERAPY

LOCATION: 3-109-4-L

MAJOR EQUIPMENT:

1-Whirlpool bath, leg

2-Baker light 3-Infrared lamp

#### PHARMACY

LOCATION: 3-119-1-Q

CAPABILITY: Routine dispensing of drugs and medications.

MAJOR EQUIPMENT:

4-Distilling apparatus 1-Locker, Safe-Type 1

2-Acid locker 5-Shelving

3-Refrigerator, Type III

#### CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 3-113-1-Q

Autoclaves by type: 1-Sterilizer, Surgical instrument 6530-973-9716 2-Sterilizer, Pressure type I size 3

DENTAL\_X-RAY (Fixed)

LOCATION: 3-113-2-Q

MAJOR EQUIPMENT:

1-X-Ray tank master
2-X-Ray darkroom cabinet
3-Dental operating chair
4-Dental X-Ray unit
5-Dental X-Ray viewbox
6-X-Ray drier

#### USS MOUNT WHITNEY

LCC-20

#### COMPLEMENT:

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
2200 Den Officer	LT
Various	9 - HM
0000	2 - DT 2

Note: Complement not yet definite.

#### STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not yet established.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None.

UNCLASSIFIED

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS GUADALCANAL LPH-7

UNCLASSIFIED

## TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Triage Area	2 3
Operating Room(s) Dedicated	
Operating Room(s) Non-Dedicated	4 5
Minor Surgery Area	5
Primary Ward	6 7
Overflow Ward	7
Quiet Room #1	8
Quiet Room #2	9
Laboratory	10
X-Ray (Fixed)	10
Dental X-Ray	10
Physiotherapy	10
Pharmacy	11
Central Supply/Sterilization Room	11
Morgue	11
Dental Operating Room #1	12
Dental Operating Room #2	13
Medical Administration	14
Medical Supply	15
Dental Supply	16
Battle Dressing Station #1	17
Battle Dressing Station #2	18
Battle Dressing Station #3	19
Battle Dressing Station #4	20
Complement	21
Status of Outstanding Shipalts	21
Size and Location of Area for Breakout of Surgical Block	21
Stowage Near Helo Pad for Replacement Litters and Blanket	s 21

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support to other ships(3) Medical support for embarked non-crew personnel

(4) Casualty receiving/evacuation

#### MEDICAL ASSETS:

	*****	
Asset	Normal Use/Type	Remarks
Triage Area	Lobby	
Operating Room(s)	Standard	
Non-Ded OR(s)	Treatment Room	Same as OR
Minor Surgery Room	Aviation Exam. Rm.	Folding table
Primary Ward	Troop Ward	19 Beds
Overflow Ward(s)	Troop Living	120 Beds
Quiet Room(s)	Ship Ward/Isol.	9 Beds
Intensive Care Unit	Primary Ward	
X-Ray	1-300 ma 1-30 ma	1-Fixed 1-Portable
Physiotherapy	Whirlpool	1-Arm 1-Leg
Pharmacy	Standard	
Blood Storage	Blood Storage	200 pints
Morgue		Use refr. as required
Dental OR	Weber P-64	2
Dental X-Ray	Weber X-Ray Unit	Film tank & dryer
Laboratory	Laboratory	
Admin. Office	Administrative	3 Desks
Supply Room	Supply	1-PT 1-STBD
Battle Dressing	Standard	4 each BDS w/folding
Stations		operating table

#### CASUALTY FLOW:

(1) Helicopter to Flight Deck to #1 aircraft elevator to Hangar Deck to electric or air hoist to triage area adjacent to Sick Bay. (2) From boat, hoist by aviation crane to #1 aircraft elevator, then same as by helicopter.

#### SIGNIFICANT DEFICIENCIES:


(1) Ship vibrates severely at 16 knots and above, to the extent that X-Ray and laboratory work must be suspended.

(2) Permanent casualty hoist from Hangar to Sick Bay is needed.
(3) Better athwartships access for Medical Spaces is needed.

TRIAGE AREA

01-111-0-L(Lobby), augmented by Hangar Deck, if needed LOCATION:

FLOOR PLAN: Not to scale



- EQUIPMENT: 1-Storage locker 2-Blood bank
- 3-Air hoist 1/2 ton
- 4-Electric hoist 1/4 ton
- 5-Large oxygen bottles
- 6-Small oxygen and nitrous oxide bottles
- 7-Small oxygen bottles

#### OPERATING ROOM (Dedicated)


LOCATION: 01-118-0-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Castle light

2-OR table

3-Sterilizer 4-Storage cabinet 5-Anesthesia equip.



#### OPERATING ROOM (non-dedicated)

LOCATION: 01-115-2-L

NORMAL USE: Treatment Room

FLOOR PLAN: Not to scale EQUIPMENT:

1-Castle light set

2-OR table 3-Vol. breathing

equip.

4-Poison locker

5-File cabinet


6-Storage cabinet

7-Scales

8-Sterilizer

9-Sink

10-Desk



#### MINOR SURGERY AREA

LOCATION: 01-123-2-L

NORMAL USE: Examining Room (Aviation)

FLOOR PLAN: Not to scale


EQUIPMENT:

1-Desk

2-File cabinet 3-Folding table 4-Water heater

5-Cabinet 6-Sink

7-Slit lamp 8-Sterilizer 9-Castle lights




#### PRIMARY WARD

LOCATION: 01-126-0-L

NORMAL USE: Troop Ward

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Beds (total 19)
2-Sterilizer
3-Desk
4-Orthopedic bed




#### OVERFLOW WARD

LOCATION: 01-131-0-L

NORMAL USE: Troop Living Space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (total 120)



## QUIET ROOM #1

LOCATION: 01-121-2-L

NORMAL USE: Ship Ward

EQUIPMENT: 1-Oxygen tent 2-Beds (total 5) FLOOR PLAN: Not to scale 3 - Desk 4-Orthopedic bed - 11' -4 2 3 10 2 - 14'-

USS GUADALCANAL LPH-7


QUIET ROOM #2

LOCATION: 01-121-1-L

NORMAL USE: Isolation Ward

FLOOR PLAN: Not to scale EQUIPMEN

EQUIPMENT: 1-Beds (total 4)



### LABORATORY

LOCATION: 01-119-1-L

CAPABILITY: Routine laboratory procedures required for diagnos-

tic studies. Whole blood storage capability of 200

pints.

MAJOR EQUIPMENT:

1-Microscope (Binocular) 6-Centrifuge, Model SBR

2-Spectronic 20 7-Flame photometer

3-Incubator 8-Refrigerator

4-Water bath 9-Variable speed rotator

5-Centrifuge, Model CL

NOTE: A drying oven is scheduled to be installed during this

yard period 6640-435-7320.

### X-RAY (fixed)

LOCATION: 01-125-1-L

MAJOR EQUIPMENT:

1-X-Ray unit 300 ma with table, transformer, and fluoro unit.

2-Tank, master 3-X-Ray dryer

4-X-Ray unit 30 ma portable

NOTE: X-ray film processor to be installed during this yard

period.

### DENTAL X-RAY

LOCATION: 01-117-3-L

MAJOR EQUIPMENT:

1-Ritter chair

2-Weber X-Ray unit 3-Morse X-Ray film tank 4-X-Ray film dryer

### PHYSIOTHERAPY

LOCATION: 01-129-2-L

MAJOR EQUIPMENT:

1-Leg whirlpool 2-Arm whirlpool

### **PHARMACY**

LOCATION: 01-115-3-L

CAPABILITY: Filling prescriptions of drugs carried in the Fed-

eral Stock Catalog. Compounding of solutions,

powders, suppositories and capsules.

**EQUIPMENT:** 

1-Knife edge balance

2-Still

3-Demineralizer

### CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 01-116-1-L

Autoclaves by type: Steam sterilizer, Pressure 35 to 75 P.S.I. (6530-973-9716)

Electric sterilizer, Pressure 33 P.S.I.

Sterilizer, boiling

Other major equipment: Portable Bovie unit

Note: Sterilizer, Pressure, High Speed - to be installed during

this yard period, Model: R-2036.

### MORGUE

LOCATION: No space specifically designated. Refrigerator(s)

would be used as required.

### DENTAL OPERATING ROOM #1

LOCATION: 01-119-3-L

 $FLOOR\ PLAN$ : Not to scale

**EQUIPMENT:** 

1-Ritter chair 2-Weber P-64 unit


3-Hamilton cabinets

4-Speed clave

5-Dri-clave 6-Surgical pump \*7-2 each Pedigo chairs

8-Sink

9-Desk



\*Not shown on drawing

### DENTAL OPERATING ROOM #2

LOCATION: 01-115-9-L

FLOOR PLAN: Not to scale

**EQUIPMENT:** 

1-Ritter chair 2-Weber P-64 unit 3-Hamilton cabinets


4-Speed clave 5-Dri-clave

\*6-Surgical pump \*7-2 each Pedigo

chairs

8-Sink

9-Desk



\* Not shown on drawing

### MEDICAL ADMINISTRATION

LOCATION: 01-117-2-Q and 01-115-6-Q

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Sink
2-Desk
3-File
4-Safe
5-Book rack
6-Visible index
cabinet (over)
7-Chair



STARBOARD

4 - 53 - 1 - A

### MEDICAL SUPPLY


LOCATION: 4-53-1-A, 4-53-2-A


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Ladder 2-Locker 3-Safe 4-Shelves

BOW

PORT 4-53-2-A





USS GUADALCANAL


LPH-7

### DENTAL SUPPLY

LOCATION: 61-115-7-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Shelves




LOCATION: 2-27-2-L

Not to scale FLOOR PLAN:

EQUIPMENT: 1-Castle lights 2-Folding table

3-Shelf 4-Sink

5-Sterilizer 6-Cabinet




LOCATION: 2-90-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Castle lights 2-Folding table 3-Cabinet

4-Sterilizer

5-Sink




LOCATION: 2-107-5-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Castle lights 2-Folding table 3-Cabinet

4-Sterilizer


5-Sink 6-Shelf



LOCATION: 03-81-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Castle lights
2-Folding table
3-Sink
4-Escape hatch
5-Sterilizer 6-Cabinets



LPH-7

### USS GUADALCANAL

### **COMPLEMENT:**

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
8405 0000	HMCS HM1
8417 (Lab)	HM2
8482 (Pharmacy)	HM2
8452 (X-Ray)	HM3
8483 (OR)	HM.3
0000 0000	HN HN
2200 Dental Officer	LT
0000	DT1
0000	DT2

### STATUS OF OUTSTANDING SHIPALTS:

LPH 224 (Casualty Elevator) - deferred
LPH 262 (Convert Surgical Dr. Rm. 01-115-2-L into O.R. #2,
rearrange Sterilizer Rm., convert 01-131-0-L into
comb. troop living space and medical overflow ward,
etc.) - deferred

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Store and breakout in Vehicle Storage, 1-111-0-AA, directly under Sick Bay.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None. Procedure is to provide from Sick Bay as needed.

### **UNCLASSIFIED**

# INVENTORY OF THE MEDICAL CAPABILITY OF THE USS GUAM LPH-9

UNCLASSIFIED

### TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	1 2
Triage Area	4
Operating Room	5
Operating Room (non-dedicated)	6
Minor Surgery Area	7
Primary Ward	8
Overflow Ward #1	9
Overflow Ward #2	10
Quiet Room	11
Laboratory	12
X-Ray	12
Dental X-Ray	12
Cast Room	13
Physiotherapy	13
Pharmacy	13
Central Supply/Sterilization Room	13
Dental Operating Room #1	14
Dental Operating Room #2	15
Medical Administration	7.6
Medical Supply	17
Dental Supply	18
Battle Dressing Station #1	19
Battle Dressing Station #2	20
Battle Dressing Station #3	21
Battle Dressing Station #4	22
Complement	23
Status of Outstanding Shipalts	23
Size and Location of Area for Breakout of Surgical Bloc	k 23
Stowage Near Helo Pad for Replacement Litters and Blank	

USS GUAM LPH-9

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support to other ships(3) Medical support for embarked non-crew personnel

(4) Casualty receiving/evacuation

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Hangar Deck	No desig. Triage
Operating Room(s)	Main Operating Room	
Non-Ded OR(s)	Surgical Dressing Room	Main BDS
Minor Surgery Room	Aviation Exam. Room	_
Primary Ward	Ships Ward	
Overflow Ward(s)	Troop Ward, Troop Berth	
Quiet Room(s)	Isolation Ward/Quiet Rm	
Intensive Care Unit		None
X-Ray	Fixed Unit 100 ma	Portable Unit 15 ma
Physiotherapy	Whirlpool Arm, Leg, Sitz	
Pharmacy	Compound/Dispense Drugs	
Blood Storage		200 Bag, 60 Bottle
Morgue	Food Storage Refrig.	None designated
Dental OR	Dental Surgery	Two ORs
Dental X-Ray	Fixed Unit	
Laboratory	Clinical Laboratory	Diagnostic Tests
Admin. Office	Administration	8 Files, 2 Desks
Supply Room	Medical Supply	Four Storerooms
Battle Dressing	Standard	Three designated
Stations		BDS + Main BDS

### CASUALTY FLOW:

(1) Helicopter to Flight Deck to #1 aircraft elevator to Hangar Deck to electric or air hoist to triage area adjacent to Sick Bay. (2) From boat, hoist by aviation crane to #1 aircraft elevator, then same as by helicopter.

### SIGNIFICANT DEFICIENCIES:

Not determined

USS GUAM LPH-9

### MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
l l	01-129-2-A	Medical Storeroom
1	01-130-2-1	Physiotherapy Room
3	01-127-2-Q	Fan Room
.1	01-123-2-L	Aviation Examining Room
5		Consultation Room
6		Cleaning Gear Locker
7		Linen Locker
8	01-117-2-Q	Medical Dept. Office
9	01-115-6-Q	Medical Dept. Records Office
10		Fan Room
11		Casualty Collecting Station
• •		δ Sick Bay Lobby
1.2		Passage
13	01-115-2-L	Surgical Dressing Room &
• •	01 110 2 E	Battle Dressing Station
14	01-119-0-L	Operating Room
15	01-122-2-L	Ship Ward
16		Diet Pantry
17	01-127-0-L	Troop Ward
18		Utility Room
19	- <b>-</b>	Troop Ward Bath
20		Ship Ward Bath
21		Isolation Ward or Quiet
21		Room Bath
22	01-117-1-L	Sterilizing Room
23		Apparatus Room
24	01-115-3-L	Pharmacy
25	01-118-1-A	Medical Storeroom
26	01-120-1-L	Laboratory
27	01 - 1 2 2 - 1 - L	Isolation Ward or Quiet Room
28	01-126-1-L	Medical X-Ray Room
29	01 120 1 11	X-Ray Dark Room
30		Dental Department Office
31	01-119-1-L	#2 Dental Operating Room
32	01-118-1-L	Dental X-Ray Room
33		X-Ray Dark Room
34	01-115-9-L	#1 Dental Operating Room
35	01-115-3-E 01-115-7-A	Dental Storeroom
36 36	01-113-7-X	Anteroom
37		
<i>31</i>	<del></del>	Passage


Compartment numbers are not shown in some cases because they do not appear on the available plan.

(See Floor Plan, Page 3)

### MAJOR MEDICAL SPACE OVERVIEW

FLOOR PLAN: Not to scale

(See Reference, Page 2)



### TRIAGE AREA

LOCATION: 01-111-0-L (Lobby), augmented by Hangar Deck, if needed.

FLOOR PLAN: Not to scale

## $\Box 6$ I I 48 1 2 3 4 17'

- EQUIPMENT: 1-Storage locker 2-Blood bank
- 3-Air hoist 1/2 ton 4-Electric hoist
- 1/4 ton
- 5-Large oxygen bottles
- 6-Small oxygen and nitrous oxide bottles
- 7-Small oxygen bottles

### OPERATING ROOM

LOCATION: 01-119-0-L

FLOOR PLAN:

EQUIPMENT: I-Instrument and dressing stand

2-Operating table, pede tal

3-Castle lights 4-X-Ray film viewer

5-Emerson ventilatorrespirator


6-llyfrecator

7-Anesthesia machine

8-Suction and pressure apparatus

9-Portable X-Ray 15ma

10-Static conductive linoleum




### OPERATING ROOM (non-dedicated)

LOCATION: 01-115-2-1

NORMAL USE: Surgical Dressing Room

FLOOR PLAN:



### **EQUIPMENT:**

I-Electric baker

2-Sterilizer & shelf

3-Water heater 4-Scrub sink

5-X-Ray view box

b-Medical locker

7-Instrument and dressing stand

8-Chair

9-Log desk 10-book rack

11-Examining and treatment chair 12-Antidote locker

13-File cabinet

14-Infra-red lamp

15-Cabinet and locker type "A"

16-Scale

17-Operating table

18-Castle lights

19-Defibrillator

20-Static conductive

floor

### MINOR SURGERY AREA

<u>LOCATION</u>: 01-123-2-L


NORMAL USE: Examining Room (Aviation)

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Desk 2-File cabinet 3-Folding table 4-Water heater 5-Cabinet

6-Sink

7-Slit lamp 8-Sterilizer 9-Castle lights




### PRIMARY WARD

LOCATION: 01-122-2-I.

NORMAL USE: Ship's ward

FLOOR PLAN:

EQUIPMENT: 1-Orthopedic bed 2-Bunks (2 high) 3-Desk



### OVERFLOW WARD #1


01-127-0-L LOCATION:

NORMAL USE: Troop Ward

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Beds (total 19)
2-Sterilizer
3-Desk

4-Orthopedic Bed




### OVERFLOW WARD #2

LOCATION: 01-131-0-L

NORMAL USE: Troop Living Space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (total 108)



USS GUAM LPH-9


QUIET ROOM

<u>LOCATION</u>: 01-122-1-L

NORMAL USE: Isolation Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (total 4)



### LABORATORY

LOCATION: 01-120-1-L

All routine clinical, biochemical, hematological, and bacteriological determinations. Regular cross-matching and blood donor procedures. CAPABILITY:

Blood Storage Capability: 200 bags; 60 bottles

### MAJOR EQUIPMENT:

1.	Microhematocrit reader	8.	Rotator, VDRL
2.	Small centrifuge	9.	Pipette shaker
3.	Water bath	10.	Flame photometer
4.	Microcapillary centrifuge	11.	Spectro photometer
5.	Bacteriological incubator	12.	Blood bank refrigerator
6.	Drying oven	13.	Binocular microscope
7.	Shaking machine	14.	Colorimeter

### X-RAY

LOCATION: 01-126-1-L

### MAJOR EQUIPMENT:

- 1. Fixed X-Ray table with Buckey 100ma/100kv unit

- X-Ray dryer
   Field type processing tanks
   Automatic film processor to be installed

### DENTAL X-RAY

LOCATION: 01-118-1-L

### MAJOR EQUIPMENT:

- 1. Dental chair 5. Dryer 2. X-Ray unit3. Tank-developer 6. Safe light 7. X-Ray light
- 4. Water fixer

USS GUAM LPH-9

### CAST ROOM

LOCATION: 01-123-2-L

CAPABILITY: Routine extremity casting with limited body applica-

tion. This area normally used as Aviation Examining

Room.

### PHYSIOTHERAPY

LOCATION: 01-130-2-L

CAPABILITY: Physiotherapy for extremities

### MAJOR EQUIPMENT:

1. Arm whirlpool bath

2. Leg whirlpool bath

3. Sitz bath

### PHARMACY

LOCATION: 01-115-3-L

CAPABILITY: Compounding and dispensing drugs

### MAJOR EQUIPMENT:

1. Scales and balance

### CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 01-117-1-L

Autoclaves by type:

AMSCO Auto

American-steam heat

Portable pressure sterilizer

### DENTAL OPERATING ROOM #1

LOCATION: 01-115-9-L

FLOOR PLAN: Not to scale

EQUIPMENT:

1-Ritter chair 2-Weber P-64 unit 3-Hamilton cabinets

4-Speed clave 5-Dri-clave

6-Surgical pump \*7-2 each Pedigo chairs

8-Sink

9-Desk

10-Instrument cabinet

11-Amalgamator

\*Not shown on drawing

### DENTAL OPERATING ROOM #2

LOCATION: 01-119-1-L

FLOOR PLAN: Not to scale

**EQUIPMENT:** 

1-Ritter chair 2-Weber P-64 unit 3-Hamilton cabinets

4-Speed clave


5-Dri-clave

6-Surgical pump \*7-2 each Pedigo chairs

8-Sink

9-Desk

10-Amalgamator



\*Not shown on drawing


### MEDICAL ADMINISTRATION

LOCATION: 01-117-2-Q and 01-115-6-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Sink 2-Desk 3-File 4-Safe

5-Book rack 6-Visible index cabinet (over) 7-Chair



LPH-9 USS GUAM

### MEDICAL SUPPLY

LOCATION: 4-53-2-A, 01-129-2-A, 01-118-1-A, 2-107-5-L


FLOOR PLAN:

EQUIPMENT:


2-Safe

3-Shelves

Storeroom #1 - Bulk Supplies, Blankets, Battle Dressings, Linen (4-53-2-A)




Storeroom #2 - High Usage Items, Evacuation Supplies, Casting Supplies, IV Fluids, Sutures, Bandages, Needles; (01-129-2-A)Syringes



Storeroom #3 - Pharmacy Supplies, Locker, Safe

(01-118-1-A)



Storeroom #4 - Battle Dressing Station #3, Compt. 2-107-5-L

USS GUAM


LPH-9

### DENTAL SUPPLY

LOCATION: 01-115-7-A

FLOOR PLAN: Not to scale

EQUIPMENT: 7-Shelves



USS GUAM

LPII-9

### BATTLE DRESSING STATION #1


<u>LOCATION</u>: 2-27-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Castle lights 2-Folding table

3-Shelf 4-Sink

5-Sterilizer 6-Cabinet



USS GUAM


LPH-9

### BATTLE DRESSING STATION #2

LOCATION: 2-91-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Castle lights
2-Folding table
3-Cabinet
4-Sterilizer
5-Sink



USS GUAM LPH-9

### BATTLE DRESSING STATION #3

LOCATION: 2-107-5-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Castle lights 2-Folding table NOTE: Also serves as Medical Storeroom #4

3-Cabinet

4-Sterilizer

5-Sink 6-Shelf




#### BATTLE DRESSING STATION #4

LOCATION: 03-82-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Castle lights
2-Folding table
3-Sink

4-Escape hatch 5-Sterilizer 6-Cabinets



USS GUAM LPH-9

#### COMPLEMENT

SPECIA	LTY	RANK	OR	RATE
2100	(GMO)	LT		
0000		HMC	5	
0000		HM1		
8417	(Lab)	HM 2		
8482	(0.R.)	HM2		
8452	(X-Ray)	HM3		
8483	(Pharmacy)	HM3		
0000	•	HN		
0000		HN		
2200	(Dental)	LT		
0000		DT1		
0000		DT2		

#### STATUS OF OUTSTANDING SHIPALTS:

None identified.

#### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Store and breakout in vehicle storage, 1-111-0-AA, directly under Sick Bay.

#### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None identified.

UNCLASSIFIED

THE MENCAL AND MAKE THE MENCAL AND T

USS INCHON LPH-12

This ship is deployed and the questionnaire has not been returned. In the future, after the receipt of the questionnaire, the additional information can be inserted to augment that taken from the Booklet of General Plans.

USS INCHON LPH-12

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
1	01-130-2-Q	Medical Property Office
2	01-127-2-L	Physiotherapy Room
3	01 - 123 - 2 - L	Bacteriological Laboratory
4	01-122-2-A	Medical Storeroom
2 3 4 5	01-119-6-L	Medical X-Ray
b	01-118-2-L	X-Ray Dark Room
7	01-115-6-L	Pharmacy
8	01 - 125 - 4 - Q	Diet Pantry
9	01 - 122 - 0 - L	Ward #1
10	01-119-4-Q	Medical Department Office
$\overline{11}$	01-115-2-L	Surgical Dressing Room and
		Battle Dressing Station
12	01-111-0-L	Casualty Collecting Station
<del></del>	11 11 3 2	and Ward Lobby
13	01-127-0-L	Ward #2
14	01-125-2-L	Utility Room
15	01-120-0-L	Consultation Room
16	01-119-2-L	Consultation Room
17	01-125-0-L	Ward Bath
18	01-125-1-L	Quiet Room Bath
19	01-122-1-L	Quiet Room
20	01-120-1-Q	Apparatus Room
21	01-118-1-L	Sterilizer Room
22	01-115-1-L	Scrub Room
23	01-119-1-Q	Medical Department Record
	`	Office
24	01-115-3-L	Operating Room
25	01-124-1-L	Examining Room
26	01-122-3-Q	Dental Department Office
27	01-119-3-L	Dental Operating Room #2
28	01-118-3-L	Dental X-Ray Cubicle
29	01-118-3-L	Dental X-Ray Dark Room
30	01-115-9-L	Dental Operating Room #1
31	01-115-7-A	Dental Storeroom
32		Non-medical space


(See Page 3 for Floor Plan)

USS INCHON LPH-12

## MAJOR MEDICAL SPACE OVERVIEW

FLOOR PLAN: Not to scale

(See Page 2 for References)



# UNCLASSIFIED

# TABLE OF CONTENTS

<u>ltem</u>	Page No.
Tactical Mission	1
Medical Mission	ī
Medical Assets	
Casualty Flow	î
Significant Deficiencies	ī
Major Medical Space Gverview	2
Triage Area	1 1 2 3 4
Minor Surgery Area	4
Primary Ward	Ś
Overflow Ward #1	6
Overflow Ward #2	5 6 7
Laboratory	8
X-Ray '	8
Cast Room	8
Pharmacy	8
Central Supply/Sterilization Room	8
Medical Administration	9
Medical Supply (3rd Deck)	10
Medical Supply (4th & 7th Deck)	11
Dental Operating Room	12
Battle Dressing Station *1	13
Battle Dressing Station #2	14
Battle Dressing Station #3	15
Complement	16
Status of Outstanding Shipalts	16
Size and Location of Area for Breakout of Surgical Block	
Stowage Near Helo Pad for Replacement Litters and Blanker	ts 16

USS RALEIGH

LPD-1

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Upper Veh.Storage(Boat)	
Operating Room(s) Non-Ded OR(s)		None None
Minor Surgery Room	Main BDS	None
Primary Ward	Medical Ward	12 Beds
Overflow Ward(s)	(2)Crews Living Space	86 Beds (total)
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray	Picker Portable 15 ma	
Physiotherapy		None
Pharmacy	Main BDS	Simple Compounding
Blood Storage		None
Morgue	None Designated	Use Food Storage
Dental OR	Dental OR	
Dental X-Ray	Fixed Unit in Dent.OR	Routine
Laboratory	Main BDS	Tests
Admin. Office	Medical Administration	
Supply Room	(4) Medical Supply	(1) Dental
Battle Dressing Stations	Standard Equipment	Three BDS

#### CASUALTY FLOW:

(1) Casualties received by boat are triaged in upper vehicle

(2) Casualties received by helo are triaged on Port Mess Deck.


#### SIGNIFICANT DEFICIENCIES:

None reported by ship.

USS RALEIGH

## MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
1	<del>2 - 1 4 4 - 2 -</del> Q	Medical Records Office
2	2-142-2-A	Medical Storeroom
3	2-136-4-L	X-Ray Dark Room
4	2-120-4-L	Ward
5	2-116-2-L	Ward Bath
6	2-113-2-L	Dental Supply
7	2-108-4-L	Dental OR & X-Ray
8	2-101-2-L	Pharmacy & Midship Battle
		Dressing Station
9	2 - 96 - 4 - Q	Medical Department Records
		Office




USS RALEIGH LPD-1

#### TRIAGE AREA


Upper Vehicle Storage, 22' overhead Port Mess Deck, 10' overhead LOCATION:

FLOOR PLAN: Not to scale

EQUIPMENT: (Non-Fixed)
1-Portable medical locker (not shown on drawing)



Unper Vehicle Storage Triage for Casualties Received by Boat



Port Mess Deck Triage Area for Casualties Received by Air


#### MINOR SURGERY AREA

LOCATION: 2-101-2-L

NORMAL USE: Main Battle Dressing Station, Pharmacy, Laboratory,

Cast Room

FLOOR PLAN: Not to scale



#### **EQUIPMENT:**

- I-Pharmacy cabinet & work table
- 2-Cabinet 65"x42"x22"
- 3-Cabinet-table
- 4-Laboratory incubator
- 5-Operating table
- 6-Counter-top refrigerator
- 7-Castle lights
- 8-Sink
- \* Portable resusci-tators (2) \* Burdick Defibrilla-
- \* Cambridge VS-III portable EKG
- \* Not shown on drawing

#### PRIMARY WARD

LOCATION: 2-120-4-L

NORMAL USE: Medical Ward

FLOOR PLAN:

EQUIPMENT: 1-Bunk 2-Locker 3-Portable X-Ray stowage 7 4-Refrigerator 5-Desk 6-Cabinet 7-Ward head 6 1 2 5 32 ' 1 4 2 1 1 2 2 1 1

9


# OVERFLOW WARD #1

LOCATION: 2-68-2-L

NORMAL USE: Crew's living space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunks 2-Lockers



USS RALEIGH LPD-1


## OVERFLOW WARD #2

<u>LOCATION</u>: 2-64-0-Q

NORMAL USE: Crew's living space

 $\underline{\text{FLOOR PLAN}}$ : Not to scale

EQUIPMENT: 1-Bunks 2-Lockers



USS RALEIGH

LPD-1

#### LABORATORY

LOCATION: 2-101-2-L (Main Battle Dressing Station)

CAPABILITY: Routine CBC, urinalysis, cultures, water analysis, VDRL, RPR, gram stain. No blood storage capability.

MAJOR EQUIPMENT:

- B&L binocular microscope
   Laboratory centrifuge
   Micro hematocrit 4. VDRL bath 5. Incubator 6. Demineralizer

#### X - RAY

LOCATION: Portable unit

MAJOR EQUIPMENT:

- 1. 15 ma Picker portable unit 4. Film storage bin 2. Developing & fixing tank 5. Viewers (2)

3. Film dryer

#### CAST ROOM

LOCATION: 2-101-2-L (Main Battle Dressing Station)

CAPABILITY: Apply and remove extremity casting.

MAJOR EQUIPMENT: 1. Cast Cutter

#### PHARMACY

LOCATION: 2-101-2-L (Main Battle Dressing Station)

CAPABILITY: Compounding simple preparations, weighing and measuring, dispensing controlled and non-controlled drugs.

#### MAJOR EQUIPMENT:

- 1. Torsion balance
- 2. Pharmacy scale

#### CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 2-96-2-L (passageway)

Autoclaves by Type:

- 1. AMSCO sterilizer (1)
- 2. Wilmot Castle Speed-clave #777

USS RALEIGH LPD-1


#### MEDICAL ADMINISTRATION

<u>LOCATION</u>: 2-96-4-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Files (3) 2-Desk with type-

writer 3-"Visible" files(3)



USS RALEIGH LPD-1


#### MEDICAL SUPPLY

LOCATION: 2-142-2-A, 3rd Deck


FLOOR PLAN: Not to scale

EQUI?MENT: 1-Shelves 2-Safe

Medical Storeroom - Drug Storage (2-142-2-A)



Medical Storeroom - Storage for Drugs, Parenteral Fluids, Instru-(3rd Deck) ments and Bandages



#### MEDICAL SUPPLY


LOCATION: 4th Deck, 7th Deck

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Dehumidifier 2-Acid locker 3-Safe

3-Sate 4-Shelves

Medical Storeroom (4th Deck) Storage for Bulk Fluids, Instruments & Bandages, Drugs, Parenteral Fluids.



Medical Storeroom (7th Deck) Storage for Laboratory Materials, Linens and Miscellaneous goods.



#### DENTAL OPERATING ROOM


LOCATION: 2-108-4-L

FLOOR PLAN: Not to scale

#### **EQUIPMENT:**

1-Ritter unit

- 2-Ritter chair 3-Dental cabinet
- 4-SS White X-Ray unit
- 5-Bramson autoclave
- 6-Dri-Therm sterilizer
- 7-Weber AT-200
- 8-Sink
- 9-Desk



USS RALEIGH LPD-1

## BATTLE DRESSING STATION #1

<u>LOCATION</u>: 2-101-2-L

FLOOR PLAN: Same as Minor Surgery Area <u>EQUIPMENT</u>

EQUIPMENT: Same as Minor Surgery Area

LPD-1 USS RALEIGH

#### BATTLE DRESSING STATION #2

LOCATION: 2-36-0-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Medical supply

cabinet

2-Operating table
3-Castle lights
4-Work bench
5-Water tank

6-Sink 7-Battle lanterns 8-Crew's lockers



#### BATTLE DRESSING STATION #3

LOCATION: 2-208-2-L

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Medical supply

cabinet

2-Operating table 3-Castle lights 4-Work bench

5-Water tank

6-Sink 7-Battle lanterns



USS RALEIGH

LPD-1

#### COMPLEMENT:

SPECIALTY	RANK OR RATE
2100	LT MC
8406	НМС
8483	HM1
8482	HM 2

#### STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

UNCLASSIFIED

# TABLE OF CONTENTS

<u>ltem</u>	Page No	<u>.</u>
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1 1 2 3	
Major Medical Space Overview	2	
Triage Area	3	
Operating Room	4	
Minor Surgery Area	4 5	
Prinary Ward	6	
Overflow Ward #1	7	
Overflow Ward #2	8	
Overflow Ward #3	9	
Laboratory	10	
X-Ray	10	
Pharmacy	10	
Central Supply/Sterilization Room	10	
Dental X-Ray	10	
Medical Administration	11	
Medical Supply (2nd & 3rd Deck)	12	
Medical Supply (4th & 7th Deck)	13	
Dental Operating Room	14	
Battle Dressing Station #1	15	
Battle Dressing Station #2	16	
Battle Dressing Station #3	17	
Complement	18	
Status of Outstanding Shipalts	18	
Size and Location of Area for Breakout of Surgical Block	18	
Stowage Near Helo Pad for Replacement Litters and Blanket	s 18	

LPD-3

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	Upper Vehicle Storage	Port Mess Deck
Operating Room(s)	Major Surgery	
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Medical Ward	12 Beds
Overflow Ward(s)	(3) Troop Living Space	56 Beds (total)
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray	Picker Portable 50ma	
Physiotherapy		None
Pharmacy	Main BDS	
Blood Storage	Laboratory	16 Units
Morgue	None Designated	Use Food Refrig.
Dental OR	Dental Surgery	
Dental X-Ray	In Dental OR	
Laboratory	Clinical Laboratory	Routine Tests
Admin. Office	Medical Administration	6 Files, 2 Desks
Supply Room	(4) Medical Supply	
Battle Dressing Stations	Standard Equipment	Three BDS

#### CASUALTY FLOW:

(1) Casualties received by boat are triaged in upper vehicle

(2) Casualties received by helo are triaged on Port Mess Deck.


## SIGNIFICANT DEFICIENCIES:

Need additional medical personnel.

LPD-3

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
1	2-144-2-L	Dental OR
2	2 - 1 4 0 - 2 - L	X-Ray Dark Room
3	2 - 1 <b>3</b> 7 - 2 - L	Laboratory
4	2 - 1 2 0 - 4 - L	Ward
5	2 - 1 1 6 - 2 - L	Ward Bath
b	2-113-2-L	Head
7	2-108-2-L	Operating Room
8	2-101-2-L	Pharmacy & Midship Battle
		Dressing Station
9	2 - 96 - 4 - Q	Medical Department Records
		Office




#### TRIAGE AREA

Upper Vehicle Storage, 22' overhead, Port Mess Deck, 10' overhead LOCATION:


FLOOR PLAN: Not to scale

EQUIPMENT:(Non-Fixed)
\*I-Portable medical locker

\*Not shown on drawing.



Upper Vehicle Storage Triage for Casualties Received by Boat.



Port Mess Deck Triage Area for Casualties Received by Air.

LPD-3

## OPERATING ROOM


LOCATION: 2-108-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table

2-Anesthesia cart 3-Bovie machine
4-Conductive tile
5-Castle lights
6-Portable suction

7-Cabinets




#### MINOR SURGERY AREA

LOCATION: 2-101-2-L

Main Battle Dressing Station, Pharmacy, Laboratory NORMAL USE:

Cast Room

FLOOR PLAN: Not to scale



## EQUIPMENT:

- 1-Pharmacy cabinet & work table
- 2-Cabinet 65"x42"x22"
- 3-Cabinet-table
- 4-Laboratory incubator
- 5-Operating table
- 6-Counter-top refrigerator
- 7-Castle lights
- 8-Sink
- \* Portable resuscitators (2)
  \* Burdick defibrilla-
- tor
- \* Cambridge VS-III portable EKG


\*Not shown on drawing

# PRIMARY WARD

LOCATION: 2-120-4-L

NORMAL USE: Medical Ward

FLOOR PLAN:




#### OVERFLOW WARD #1

LOCATION: 2-160-2-L

NORMAL USE: Troop Space

FLOOR PLAN: Not to scale

EQUIPMENT 1-Bunks (18)




# OVERFLOW WARD #2

<u>LOCATION</u>: 2-176-2-L

NORMAL USE: Troop Space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunks (22)



LPD-3


#### OVERFLOW WARD #3

<u>LOCATION</u>: 3-108-2-L

NORMAL USE: Troop Space

FLCOR PLAN: Not to scale

EQUIPMENT: 1-Bunks (16)



#### LABORATORY

LOCATION: 2-137-2-L

CAPABILITY: Routine Laboratory Procedures

Blood Storage Capability - 16 units

MAJOR EQUIPMENT:

1-Binocular microscope 5-Timer

2-Incubator 6-Counter top refrigerator

3-Centrifuge 7-Millipore filter 4-Microhematocrit 8-Clinical shaker

X-RAY

LOCATION: 2-140-2-L (Dark Room)

MAJOR EQUIPMENT:

1-50ma Picker portable unit 4-View box 2-Master processing tank 5-Safety light

3-Film dryer 6-Timer

PHARMACY

LOCATION: 2-101-2-L (Main Battle Dressing Station)

CAPABILITY: No compounding capability

CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 2-108-2-L

Autoclaves by Type: 1-Amsco sterilizer

DENTAL X-RAY

LOCATION: 2-144-2-Q (Dental Operating Room)

MAJOR EQUIPMENT:

1-SS White X-ray unit


USS LA SALLE

# MEDICAL ADMINISTRATION

LOCATION: 2-96-4-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Files (3) 2-Desk with typewriter 3-"Visible" files(3)



USS\_LA\_SALLE LPD-3


### MEDICAL SUPPLY

LOCATION: 2-91-1-A, 3-140-2-A, 4-89-2-A, 7-52-0-A


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Shelves 2-Safe

Medical Storeroom - Drug Storage (2-91-1 A)



Medical Storeroom - Storage for Drugs, Parenteral Fluids, Instru-(3-140-2-A) ments and Bandages



### MEDICAL SUPPLY

LOCATION: 4-89-2-A, 7-52-0-A


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Dehumidifier 2-Acid locker 3-Safe


4-Shelves

Medical Storeroom (4+89-2-A)

Storage for Bulk Fluids, Instruments & Bandages, Drugs, Parenteral



Medical Storeroom (7-52-0-A) Storage for Laboratory Materials, Linens and Miscellaneous goods.



USS LA SALLE LPD-3

#### DENTAL OPERATING ROOM

LOCATION: 2-144-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-SS White X-ray unit
2-Weber model B unit
3-Weber model FLH chair


4-Doctor's stool

5-Sink

6-Dental instrument cabinet

7-Shelf

8-Dri-clave sterilizer 9-Weber AT-200




USS LA SALLE

# BATTLE DRESSING STATION #1

LOCATION: 2-208-1-L

FLOOR PLAN: Not to scale

EQUIPMENT: Standard BDS Equipment



LOCATION: 2-36-0-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Medical supply


cabinet

2-Operating table 3-Castle lights 4-Work bench

5-Water tank

6-Sink

7-Battle lanterns 8-Crew's lockers




USS LA SALLE LPD-3

### BATTLE DRESSING STATION #3

LOCATION: 2-208-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Medical supply
cabinet
2-Operating table
3-Castle lights
4-Work bench
5-Water tank
6-Sink
7-Battle lanterns



USS LA SALLI.

LPD-3

### COMPLIMENT:

SPECIALTY	RANK OR RATE
2100	LT MC
8406	HMC
8483	HM1
8482	11M2

### STATUS OF OUTSTANDING SHIPALTS:

Intercom in medical spaces to be installed during next overhaul.

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Upper v licle storage.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Exchange made at Helo Pad; basic supply is kept in upper vehicle storage.

# INVENTORY OF THE MEDICAL CAPABILITY OF THE USS AUSTIN LPD-4

USS AUSTIN

# TABLE OF CONTENTS

<u>Item</u>	Page	No.
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Major Medical Space Overview	2	
Triage Area	3	
Operating Room	4	
Minor Surgery Area	5	
Primary Ward	2 3 4 5 6 7	
Dental Operating Room	7	
Laboratory	8 8 8 9	
X-Ray (Portable)	8	
Pharmacy	8	
Sterilization Room	8	
Medical Administration	9	
Battle Dressing Station #1	10	
Battle Dressing Station #2	11	
Battle Dressing Station #3	12	
Complement	13	
Status of Outstanding Shipalts	13	
Size and Location of Breakout Area for Surgical Block	13	
Stowage Near Helo Pad for Replacement Litters and Blank	ets13	

USS AUSTIN

LPD-4

#### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Crew & troop mess	
Operating Room(s)	Major surgery	
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Ward	12 beds
Overflow Ward(s)		None
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray	Portable	2 units (15 ma)
Physiotherapy		None
Pharmacy	Main BDS	Routine drugs
Blood Storage		Limited
Morgue	Refrigerators	
Dental OR	Complete unit	
Dental X-Ray	Fixed unit	In Dental OR
Laboratory	Clinical laboratory	Routine tests
Admin. Office	Administration	
Supply Room	Record office	
Battle Dressing	Standard equipment	3 BDS
Stations	· ·	

### CASUALTY FLOW:

(1) Fight deck to triage area to Sick Bay via elevator.(2) Well deck to triage area via elevator to Sick Bay.


### SIGNIFICAMT DEFICIENCIES:


None reported by ship

USS\_AUSTIN LPD-4

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
I	2-154-2-A	Medical Storeroom
)	2 - 152 - 2 - Q	Gear Locker
3	2 - 144 - 4 - Q	Dental Operating Room
4	2 - 138 - 2 - L	X-Ray Dark Room
5	2 - 140 - 2 - Q	Medical Record Office
6	2 - 136 - 2 - Q	Bacteriological Laboratory
7	2-132-4-L	Ward Bath
8	2 - 116 - 2 - 1.	Ward
9	2-113-2-L	Sterilizing Room
10	2 - 108 - 4 - 1.	Operating Room
11	2 - 1 0 1 - 2 - L	Minor Surgery Area
12	2-96-4-Q	Medical Department Office





USS AUSTIN LPD-4

### TRIAGE AREA

<u>LOCATION</u>: 1-84-0-L

FLOOR PLAN:

A large area just forward of the helicopter landing area normally used for the crew and troop mess. Area exceeds 1600 square feet of floor space.

**EQUIPMENT:** 

1-Portable X-Ray

unit

LPD-4 USS AUSTIN

### OPERATIN; ROOM

LOCATION: 2-108-4-L

NORMAL USE: Operating Room

FLOOR PLAN: Not to scale

EQUIPMENT:


1-Operating table

2-Cabinets

3-Dresser

4-Surgical lights 5-Basin ring 6-Portable X-Ray

15 ma 7-Sterilizing and scrub room



USS AUSTIN

<u>LPD-4</u>

# MINOR SURGERY AREA


LOCATION: 2-101-2-L

NORMAL USE: Surgical Dressing Room and Main BDS

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Examining table 2-Lights 3-Water tank

4-Sink



USS AUSTIN

LPD-4

### PRIMARY WARD

LOCATION: 2-116-2-L

NORMAL USE: Patient care ward

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Bed unit - 3 beds

high 2-Bed unit - 2 beds

high

3-Toilet area

4-Shelf



USS AUSTIN **LPD-4** 

### DENTAL OPERATING ROOM

LOCATION: 2-144-4-Q

NORMAL USE: Dental OR and X-Ray

FLOOR PLAN: Not to scale

EQUIPMENT: 1-SS White Space-

saver X-Ray unit 2-Ritter, Model C, Type I dental OR

unit

3-Ritter Vega Air-glide dental OR chair


4-Ritter Speedclave sterilizer

5-Torit Amalgamator

6-Dentsply cavitron 7-Cabinet

8-Sink

9-Typing stand



USS AUSTIN LPD-4

#### LABORATORY

LOCATION: 2-136-2-Q

CAPABILITY: Perform routine blood and urine analysis

MAJOR EQUIPMENT:

I-Binocular microscope

2-Centrifuge

3-Hematocrit

### X-RAY (Portable)

MAJOR EQUIPMENT:

I-Two portable X-Ray units (15 ma)

2-Film processing equipment

3-Dark room 2-138-2-L

#### PHARMACY

LOCATION: 2-101-2-L

CAPABILITY: Routine ordering and dispensing of drugs

### STERILIZATION ROOM

LOCATION: 2-113-2-L

**EQUIPMENT:** 

1-Steam autoclave

USS AUSTIN


# MEDICAL ADMINISTRATION

<u>LOCATION</u>: 2-96-4-Q

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Desk
2-Book rack
3-File
4-Bookcase
5-Sink

6-Key cabinet




LOCATION: 2-36-0-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Cabinets 2-Water tank

3-Sink

4-Lamps
5-Dressing table
6-Folding table
7-Water heater



LOCATION: 2-184-1-L

FLOOR PLAN: Not to scale


 $\frac{\texttt{EQUIPMENT}}{\texttt{1-Cabinets}}$ 

1-Cabinets 2-Water tank

3-Sink 4-Lamps

5-Dressing table 6-Folding table 7-Water heater

8-Lockers 9-Sterilizer



LOCATION: 2-232-2-L


FLOOR PLAN: Not to scale **EQUIPMENT:** 

1-Lockers

2-Water tank (overhead)

3-Sink

4-Lamps 5-Dressing table 6-Folding OR table



USS AUSTIN LPD-4

### **COMPLEMENT:**

SPECIALTY	RANK OR RATE
2100 G.M.O.	LT
2200 Dental	LT
8406 Aviation Med	HMC
8482 Pharmacy	HM1
8483 OR	HM2
0000 Dental	DT 2

#### STATUS OF OUTSTANDING SHIPALTS:

Acoustical insulation on overhead in Medical Office and Ward  $\mbox{-}\mbox{pending.}$ 

### SIZE AND LOCATION OF BREAKOUT AREA FOR SURGICAL BLOCK:

Upper vehicle stowage - Well Deck.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None

UNCLASSIFIED

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS CORONADO LPD-11

### TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1.
Significant Deficiencies	1
Major Medical Space Overview	1 2 3
Triage Area	3
Operating Room	4
Minor Surgery Room	5
Primary Ward	6
Dental Operating Room	7
Medical Administration	8
Laboratory	9
X-Ray	9
Sterilization Room	
Medical Supply	9 <b>9</b>
	10
Battle Dressing Station #1	11
Battle Dressing Station #2	12
Battle Dressing Station #3	13
Complement	
Status of Outstanding Shipalts	13
Size and Location of Breakout Area for Surgical Block	13
Stowage Near Helo Pad for Replacement Litters and Blankets	3 13

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

- (1) Medical care for ship's crew
- (2) Medical support to other ships
- (3) Medical support for embarked non-crew personnel
- (4) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area Operating Room (s) Non-Ded OR(s)	Main Mess Operating Room	Mess tbls; Port X-Ray Too small None
Minor Surgery Room Primary Ward	Dress &treat,Pharm Ward	Not usable as OR 16 Beds
Overflow Ward(s) Quiet Room(s) Intensive Care Unit		None designated Part of Primary Ward None
X-Ray Physiotherapy Pharmacy	Portable	Plus aux. equipment None In Minor Surgery
Blood Storage Morgue Dental OR	Ritter, Model C	None None Complete unit
Dental X-Ray Laboratory	SS White Spacesaver Laboratory	In Dental OR Standard lab
Admin. Office Supply Room Battle Dressing	Medical Admin. 3 Storerooms Standard	Remote location No central med. sup. 3 each
Stations		

### CASUALTY FLOW:

(1) Helicopter platform on Main Deck to adjacent triage area on Main Deck to general purpose elevator to Second Deck to primary medical space.


(2) Boat in Well Deck to general purpose elevator, to triage on Main Deck to elevator to Second Deck to primary medical space.


#### SIGNIFICANT DEFICIENCIES:

- (1) Operating Room is too small. It is crowded with an unnecessary sink and cabinets.
- (2) Medical spaces are noisy and poorly laid out.
- (3) Equipment lists are deficient. They lack essential minor surgery equipment but have an excess of non-essential equipment.

# MAJOR MEDICAL SPACE OVERVIEW

REPERENCE:	LOCATION:	FACILITY:
1	2-154-2-A	Medical Storeroom
2	2 - 1 5 2 - 2 - Q	Cleaning Gear Locker
3	2-144-4-L	Dental Operating Room
4	2 - 140 - 2 - Q	Medical Records Office
5	2 - 138 - 2 - L	X-Ray Dark Room
6	2 - 1 36 - 2 - Q	Bacteriological Laboratory
7	2-132-4-L	Ward Bath
8	2-116-2-L	Ward & Quiet Room
9	2-113-2-L	Sterilizing Room
10	2-108-4-L	Operating Room
11	2 - 10 2 - 2 - L	Surgical Dressing Room
12	2 - 96 - 4 - Q	Medical Department Office





(Assumed to be similar to  $\stackrel{LPD-11}{LPD-13}$ )

#### TRIAGE AREA

LOCATION: Main Mess Hall 1-84-0-L

FLOOR PLAN:

A large area just forward of the helicopter landing area normally used for the crew and troop mess. Area exceeds 1600 square ft. of

floor space.

EQUIPMENT:

1-Portable X-Ray

unit

### OPERATING ROOM

LOCATION: 2-108-4-L

FLOOR PLAN: Not to scale


EQUIPMENT:

1-Operating table
2-Surgical lights
3-Conductive floor
\*4-3 portable suction units
\*5-Port Bovie cauter.
\*6-Port anesth. unit

7-Cabinets

8-Sink

9-X-Ray viewbox



\* Not shown on drawing

USS CORONADO

(Assumed to be similar to  $\frac{\text{LPD-11}}{\text{LPD-13}}$ 

### MINOR SURGERY ROOM


2-102-2-L LOCATION:

NORMAL USE: Treatment Room and Pharmacy

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Examining table
2-Lights
3-Water tank

4-Sink



(Assumed to be similar to LPD-11


# PRIMARY WARD

LOCATION: 2-116-2-L

NOTE: The quiet room is incorporated into one end of the ward.

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Bed unit-3 beds
high
2-Bed unit-2 beds
high
3-Toilet area



### DENTAL OPERATING ROOM

LOCATION: 2-144-4-L

NOTE: Includes Dental X-Ray and Dental Supply

FLOOR PLAN: Not to scale

EQUIPMENT:


1-SS White Spacesaver X-Ray unit

2-Ritter, Model C,
Type I dental
operating unit

3-Ritter Vega Airglide dental
operating chair

4-Ritter Speedclave
sterilizer

5-Torit Amalgamator
6-Dentsply cavitron
7-Cabinet
8-Sink



(Assumed to be similar to  $L\overline{PD-13}$ )

#### MEDICAL ADMINISTRATION

LOCATION: 2-96-4-Q

NOTE: Medical administration and medical supply administration are combined in this office.


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Files 2-Desk

3-Typewriter

4-Table 5-Bookcase

6-Desk 7-Cabinet



USS CORONADO

LPD-11 (Assumed to be similar to LPD-13)

#### LABORATORY

LOCATION: 2-136-2-Q

**EQUIPMENT:** 

4-Agglutinating machine I-Microscope 5-Spectrophotometer 2-Hematocrit centrifuge

3-Large centrifuge

6-Milliport H<sub>2</sub>0

X - RAY

Portable - Dark Room 2-138-2-L LOCATION:

**EQUIPMENT:** 

3-X-Ray film storage container 1-X-Ray film dryer 2-X-Ray film developer tank

4-X-Ray view box

STERILIZATION ROOM

LOCATION: 2-113-2-L

**EQUIPMENT:** 

1-Small electric/gas autoclave 2-Large AMSCO cylinder autoclave

#### MEDICAL SUPPLY

Note: Three storerooms are used for medical supplies but there is no central medical supply as such. Medical supply administration is handled through the medical administration office.

(Assumed to be similar to  $\overline{LPD-11}$ 

### BATTLE DRESSING STATION #1

LOCATION: 2-36-U-L


FLOOR PLAN: Not to scale

EQUIPMENT:

1-Cabinets

2-Water tank (overhead) 3-Sink

4-Lamps
5-Dressing table
6-Folding table (folded)
7-Water heater



(Assumed to be similar to LPD-11

### BATTLE DRESSING STATION #2

LOCATION: 2-184-1-L

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Cabinets

2-Water tank

3-Sink

4-Castle lights 5-Dressing table 6-Folding table 7-Water heater

8-Lockers 9-Sterilizer



USS CORONADO

(Assumed to be similar to LPD-11

## BATTLE DRESSING STATION #3

LOCATION: 2-232-2-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Lockers

2-Water tank(overhead)

3-Sink

4-Castle lights 5-Dressing table 6-Folding OR table



#### USS CORONADO

(Assumed to be similar to LPD-13)

#### **COMPLEMENT:**

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
8406 Aviation Med Tech	HMC
8404 Field Med Tech	HM1
8482 Płarmacy Tech	HM2
0000 Striker	SN
2200 Dental Officer	LT
0000 General	DT1

NOTE: Complement is one man too small and contains wrong specialties. It should include a Laboratory Assistant and an Operating Room Technician. There is no requirement for a Pharmacy Technician.

## STATUS OF OUTSTANDING SHIPALTS:

Not determined.

## SIZE AND LOCATION OF BREAKOUT AREA FOR SURGICAL BLOCK:

None necessary, as ship is not assigned a Surgical Team.

## STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Stowage is provided for litters, but not blankets.

# UNCLASSIFIED

THE MEDICAL CHARBEITS

THE MEDICAL CHARBEITS

INC. LEGISLES

LEGISLES

## TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Triage Area	3
Operating Room	4
Minor Surgery Room	5
Primary Ward	1 2 3 4 5 6 7
Dental Operating Room	7
Medical Administration	8
Laboratory	8 9 9 9
X-Ray	9
Sterilization Room	9
Medical Supply	9
Battle Dressing Station #1	10
Battle Dressing Station #2	11
Battle Dressing Station #3	12
Complement	13
Status of Outstanding Shipalts	13
Size and Location of Breakout Area for Surgical Block	13
Stowage Near Helo Pad for Replacement Litters and Blanket	s 13

## TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION:

- (1) Medical care for ship's crew
- (2) Medical support to other ships
- (3) Medical support for embarked non-crew personnel
- (4) Casualty receiving/evacuation

## MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Main Mess	Mess tbls; Port X-Ray
Operating Room(s)	Operating Room	Too small
Non-Ded OR(s)		None
Minor Surgery Room	Dress &treat,Pharm	Not usable as OR
Primary Ward	Ward	16 Beds
Overflow Ward(s)		None designated
Quiet Room(s)		Part of Primary Ward
Intensive Care Unit		None
X-Ray	Portable	Plus aux. equipment
Physiotherapy		None
Pharmacy		In Minor Surgery
Blood Storage		None
Morgue		None
Dental OR	Ritter,Model C	Complete unit
Dental X-Ray	SS White Spacesaver	
Laboratory	Laboratory	Standard lab
Admin. Office	Medical Admin.	Remote location
Supply Room	3 Storerooms	No central med. sup.
Battle Dressing	Standard	3 each
Stations		· · · · · · · · · · · · · · · · · · ·

## CASUALTY FLOW:

- (1) Helicopter platform on Main Deck to adjacent triage area on Main Deck to general purpose elevator to Second Deck to primary medical space.
- (2) Boat in Well Deck to general purpose elevator, to triage on Main Deck to elevator to Second Deck to primary medical space.


## SIGNIFICANT DEFICIENCIES:


- (1) Operating Room is too small. It is crowded with an unnecessary sink and cabinets.
- (2) Medical spaces are noisy and poorly laid out.
  (3) Equipment lists are deficient. They lack essential minor surgery equipment but have an excess of non-essential equipment.

USS NASHVILLE LPD-13

## MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
1	2-154-2-A	Medical Storeroom
2	2-152-2-Q	Cleaning Gear Locker
3	2 - 1 4 4 - 4 - L	Dental Operating Room
4	2-140-2-Q	Medical Records Office
5	2 - 138 - 2 - 1.	X-Ray Dark Room
6	2 - 1 36 - 2 - Q	Bacteriological Laboratory
7	2 - 1 3 2 - 4 - L	Ward Bath
8	2 - 1 1 6 - 2 - I.	Ward & Quiet Room
9	2-113-2-L	Sterilizing Room
10	2 - 108 - 4 - L	Operating Room
11	2 - 10 2 - 2 - L	Surgical Dressing Room
12	≥ 2-96-4-Q	Medical Department Office





USS NASHVILLE LPD-13

## TRIAGE AREA

LOCATION: Main Mess Hall 1-84-0-L

FLOOR PLAN:

A large area just forward of the helicopter landing area normally used for the crew and troop mess. Area exceeds 1600 square ft. of

floor space.

EQUIPMENT: 1-Portable X-Ray

unit

## OPERATING ROOM

LOCATION: 2-108-4-L

FLOOR PLAN: Not to scale


**EQUIPMENT:** 

1-Operating table
2-Surgical lights
3-Conductive floor
\*4-3 portable suction units
\*5-Port Bovie cauter. \*6-Port anesth. unit

7-Cabinets

8-Sink

9-X-Ray viewbox



\* Not shown on drawing

USS NASHVILLE LPD-13

## MINOR SURGERY ROOM

LOCATION: 2-102-2-L


NORMAL USE: Treatment Room and Pharmacy

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Examining table

2-Lights 3-Water tank

4-Sink



USS NASHVILLE LPD-13

## PRIMARY WARD

LOCATION: 2-116-2-L


NOTE: The quiet room is incorporated into one end of the ward.

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bed unit-3 beds

high 2-Bed unit-2 beds high

3-Toilet area




## DENTAL OPERATING ROOM

LOCATION: 2-144-4-L

NOTE: Includes Dental X-Ray and Dental Supply

FLOOR PLAN: Not to scale

EQUIPMENT:
1-SS White Spacesaver X-Ray unit
2-Ritter, Model C,
Type I dental
operating unit
3-Ritter Vega Airglide dental
operating chair
4-Ritter Speedclave
sterilizer
5-Torit Amalgamator
6-Dentsply cavitron
7-Cabinet
8-Sink
9-Typing stand



USS NASHVILLE LPD-13


## MEDICAL ADMINISTRATION

LOCATION: 2-96-4-Q

Note: Medical administration and medical supply administration are combined in this office.

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Files 2-Desk 3-Typewriter 4-Table 5-Bookcase 6-Desk 7-Cabinet



USS NASHVILLE LPD-13

## LABORATORY

LOCATION: 2-136-2-Q

EQUIPMENT:

1-Microscope 4-Agglutinating machine 2-Hematocrit centrifuge 5-Spectrophotometer 3-Large centrifuge 6-Millipore H<sub>2</sub>0

X-RAY

LOCATION: Portable - Dark Room 2-138-2-L

**EQUIPMENT:** 

1-X-Ray film dryer 2-X-Ray film developer tank 3-X-Ray film storage container

4-X-Ray view box

## STERILIZATION ROOM

2-113-2-L LOCATION:

**EQUIPMENT:** 

1-Small electric/gas autoclave 2-Large AMSCO cylinder autoclave

## MEDICAL SUPPLY

Note: Three storerooms are used for medical supplies but there is no central medical supply as such. Medical supply administration is handled through the medical administration office.

LPD-13 USS NASHVILLE

## BATTLE DRESSING STATION #1

LOCATION: 2-36-0-L

FLOOR PLAN: Not to scale


EQUIPMENT:
1-Cabinets

2-Water tank (overhead)

3-Sink 4-Lamps

5-Dressing table 6-Folding table (folded)

7-Water heater



## BATTLE DRESSING STATION #2

LOCATION: 2-184-1-L

FLOOR PLAN: Not to scale


EQUIPMENT:
1-Cabinets

2-Water tank

3-Sink

4-Castle lights 5-Dressing table 6-Folding table 7-Water heater

8-Lockers 9-Sterilizer



USS NASHVILLE

LPD-13

## BATTLE DRESSING STATION #3

<u>LOCATION</u>: 2-232-2-L

FLOOR PLAN: Not to scale


## $\frac{\texttt{EQUIPMENT}}{1-\texttt{Lockers}}:$

2-Water tank(overhead)

3-Sink

4-Castle lights 5-Dressing table 6-Folding OR

table



USS NASHVILLE LPD-13

## COMPLEMENT:

SPECIALTY		RANK OR RATE
2100	Med Officer	LT
840 <b>6</b>	Aviation Med Tech	НМС
8404	Field Med Tech	HM1
8482	Pharmacy Tech	HM2
	Striker	SN
2200	Dental Officer	LT
0000	General	DT1

NOTE: Complement is one man too small and contains wrong specialties. It should include a Laboratory Assistant and an Operating Room Technician. There is no requirement for a Pharmacy Technician.

## STATUS OF OUTSTANDING SHIPALTS:

All authorized alterations are being accomplished.

#### SIZE AND LOCATION OF BREAKOUT AREA FOR SURGICAL BLOCK:

None necessary, as ship is not assigned a Surgical Team.

## STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Stowage is provided for litters, but not blankets.

# UNCLASSIFIED

## INVERTORY OF THE MEDICAL CAPABILITY OF THE USS FORT MANIEUS

Commission Commission

## TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Triage Area	3
Minor Surgery Area	4
Primary Ward	5
Medical Administration	6
Medical Supply (Forward)	7
Medical Supply (Aft)	8
Battle Dressing Station #1	9
Battle Dressing Station #2	10
Complement	11
Status of Outstanding Shipalts	11
Size and Location of Area for Breakout of Surgical Bloc	:k 11
Stowage Near Helo Pad for Replacement Litters and Blank	

## TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

## MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	Well Deck	30 ft. Overhead
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Sickbay Ward	6 Beds
Overflow Ward(s)		None
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Main BDS	
Blood Storage		None
Morgue	Food Storage Refrig.	
Dental OR		None
Dental X-Ray		None
Laboratory		None
Admin. Office	Main BDS	
Supply Room	Medical Supply	One Fore, One Aft
Battle Dressing	Main BDS/Sickbay	
Stations	Designated BDS	

## CASUALTY FLOW:

(1) From helo pad, down steep ladder, along port side, up short ladder, through crew's lounge to Sick Bay.


(2) By boat, to Main Deck port side, then follow same route as above.

## SIGNIFICANT DEFICIENCIES:

Need third Battle Dressing Station.

## MAJOR MEDICAL SPACE OVERVIEW

REFERENCE	LOCATION	FACILITY
1,	A 0101 AL A 0101 AL	Dispensary & Exam. Room Ward
3	A 0101 AL	Sick Bay Wash Room
4	A 0101 AL	Doctors & Clerical Office



USS FORT MANDAN LSD-21

## TRIAGE AREA

LOCATION: Well Deck

<u>FLOOR PLAN</u>: Open Deck

EQUIPMENT: 1-Pole litters 2-IV supports 3-Portable medical

locker

USS FORT MANDAN LSD-21

## MINOR SURGERY AKEA


LOCATION: A 0101 AL

NORMAL USE: Main Battle Dressing Station/Sick Bay

FLOOR PLAN:

EQUIPMENT: 1-Autoclave

2-Sink 3-Treatment table 4-Instrument table 5-Counter w/drawers 6-Castle lights



## PRIMARY WARD


LOCATION: A 0101 AL

NORMAL USE: Sick Bay Ward

FLOOR PLAN:

EQUIPMENT: 1-Bunks (2 high) 2-Refrigerator 3-Patient locker 4-Supply locker 5-Storage room 6-Head

7-Shower 8-Sink



USS FORT MANDAN LSD-21


## MEDICAL ADMINISTRATION

LOCATION: A 0101 AL

FLOOR PLAN:

EQUIPMENT: 1-Admin. area

2-Desk 3-File cabinet



USS FORT MANDAN LSD-21


## MEDICAL SUPPLY

LOCATION: A 203 1/2 L(Forward)

FLOOR PLAN:

**EQUIPMENT:** 

1-Small bins 2-Large bins



USS FORT MANDAN


LSD-21

## MEDICAL SUPPLY

LOCATION: B 202 AE(Aft)

FLOOR PLAN:

 $\frac{\text{EQUIPMENT}}{1\text{-Storage}}:$ 



USS FORT MANDAN LSD-21

## BATTLE DRESSING STATION #1

LOCATION: A 0101 AL

NORMAL USE: Sickbay and Minor Surgery Area

FLOOR PLAN: See Minor Surgery Area EQUIPMENT:

EQUIPMENT: See Minor Surgery

Area

USS FORT MANDAN LSD-21

## BATTLE DRESSING STATION #2


LOCATION: A 202 3/4 L

FLOOR PLAN:

EQUIPMENT: 1-Supply locker 2-Sink

3-Work Bench (shop)
4-Cleaning tank (shop)
5-Portable treatment table

6-OR lights (fixed)



USS FORT MANDAN LSD-21

## COMPLEMENT:

SPECIAL	LTY		RANK	OR R	<u>ATE</u>
8405	Ind.	Duty	1	НМС	
0000		,	1	HM1	
0000			1	HM 2	
0000			2	HM3	

## STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

# UNCLASSIFIED

# THE DEDICE OF DISTRICT USS SELECTION LIGHT CONTRIBUTION LIGHT C

UKONASSIFIED

## TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Minor Surgery Area	3
Primary Ward	4
Overflow Ward #1	5
Overflow Ward #2	6
Medical Administration	7
Medical Supply	8
Battle Dressing Station #1	9
Battle Dressing Station #2	10
Complement	11
Status of Outstanding Shipalts	11
Size and Location of Area for Breakout of Surgical Block	11
Stowage Near Helo Pad for Replacement Litters and Blankets	s 11

## TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

## MEDICAL ASSETS:

Assets	Normal Use/Type	Ŕemarks
Triage Area		None
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Ward	Six Beds
Overflow Ward(s)	CPO & R Div.berths	24 Beds
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Main BDS	
Blood Storage		None
Morgue	Food Storage Refrig.	
Dental OR		
Dental X-Ray		None
Laboratory	Main BDS	Routine Tests
Admin. Office	Main BDS	l File, l Desk
Supply Room	Medical Supply	Full IOL
Battle Dressing Stations	l Designated BDS l Main Medical space	Two total

#### CASUALTY FLOW:

(1) From helo pad, down steep ladder, along port side, up short ladder, through crew's lounge to Sick Bay.
(2) By boat, to Main Deck port side, then follow same route as

above.


## SIGNIFICANT DEFICIENCIES:

Needs third Battle Dressing Station.

MAJOR MEDICAL SPACE OVERVIEW

REFERENCE	LOCATION	FACILITY
1	FR 40-43	Dispensary and Examining Room
2	FR 36-40	Ward
3	FR 32-34	Sick Bay Wash Room
4	FR 36-40	Doctor's and Clerical Office

All spaces are on the Ol Level.



## MINOR SURGERY AREA


LOCATION: FR-40-43, 01 Level

NORMAL USE: Treatment Room/Main Battle Dressing Station

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Water still
2-Sink
3-Steam sterilizer
4-Counter with
storage
5-Storage cabinets
6-Examining table
7-Antidote locker
8-Steam autoclave
9-Castle lights

10-Battle lantern



USS SAN MARCOS LSD-25

## PRIMARY WARD

LOCATION: FR 36-40, 01 Level


NORMAL USE: Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunk 2-Cabinet

3-Locker

4-Refrigerator




# OVERFLOW WARD #1

LOCATION: FR 38-43 Starboard, 01 Level

NORMAL USE: CPO Berthing

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Bunk
2-Locker
3-Sink
4-Commode
5-Urinal
6-Cabinet



USS SAN MARCOS LSD-25

### OVERFLOW WARD #2

LOCATION: FR 43-50 Port side, 01 level


NORMAL USE: R Div Berthing

<u>FLOOR PLAN</u>: Not to scale

EQUIPMENT: 1-Bunk

2-Peacoat locker 3-Table

4-Ladder



USS SAN MARCOS LSD-25

### MEDICAL ADMINISTRATION

LOCATION: Main Medical space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Locker


2-Locker-safe

3-Desk

4-Counter deck

5-Cardex

6-File cabinet




USS SAN MARCOS LSD-25

# MEDICAL SUPPLY

LOCATION: 01 Level, Starboard

FLOOR PLAN: Not to scale  $\frac{\texttt{EQUIPMENT}}{1-\texttt{Bins}}:$ 



USS SAN MARCOS

LSD-25

### BATTLE DRESSING STATION #1

LOCATION: FR-40-43, 01 Level

NORMAL USE: Treatment Room/Main Battle Dressing Station

FLOOR PLAN: See Minor Surgery Area

EQUIPMENT:
See Minor Surgery

Area

LOCATION: FR 10-16 Forward Port side, Main Deck

NORMAL USE: Shipfitter's Shop

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Cabinet 2-Table 3-Scrub sink

4-Castle lights

USS SAN MARCOS

LSD-25

### **COMPLEMENT:**

SPECIALTY	RANK OR RATE
Medical Officer	1 LT
8405 Ind. Duty	1 HMC
0000	1 HM1
0000	1 HM2
0000	2 HM3

### STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

# UNCLASSIFIED

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS PLYMOUTH ROCK LSD-29

UNGLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Triage Area	3
Minor Surgery Area	4
Primary Ward	5
Quiet Room	6
Medical Administration	7
Medical Supply	8
Battle Dressing Station #1	9
Battle Dressing Station #2	10
Battle Dressing Station #3	11
Complement	12
Status of Outstanding Shipalts	12
Size and Location of Area for Breakout of Surgical Bloc	k 12
Stowage Near Helo Pad for Replacement Litters and Blank	

### USS PLYMOUTH ROCK

LSD-29

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Open area	No equipment
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Pharmacy & Treat Rm	Crowded
Primary Ward	Qtrs. for corpsmen	10 beds
Overflow Ward(s)	Troop spaces	275-300 total
Quiet Room(s)		2 Bunks
Intensive Care Unit		None
X-Ray		None
Physiotherapy Pharmacy		None
Pharmacy		In Minor Surgery Room
Blood Storage		None
Morgue	Crew's library	
Dental OR		None
Dental X-Ray		None
Laboratory		None
Admin. Office	Medical Admin.	2 Desks & 2 files
Supply Room	Medical Supply	Incl stores for troops
Battle Dressing	Minor Surgery Rm	Standard type
Stations	plus two others	

### CASUALTY FLOW:

(1) Helicopter pad, down narrow and steep ladder to starboard Main Deck to medical area.

(2) By boat along either side, by crane to Main Deck (starboard) or 01 Deck (port). Ladders are narrow and steep with sharp turns.


### SIGNIFICANT DEFICIENCIES:

(1) Medical spaces are not air conditioned.

(2) Portable X-Ray, laboratory and dental units are needed if ship is to have an expanded medical role.

# MAJOR MEDICAL SPACE OVERVIEW

RLEERENCL: 1 2 3	LOCATION; 1 - 132 - 1 - Q 1 - 127 - 1 - Q 1 - 124 - 3 - 1.	FACILITY: Medical Department Office Pharmacy/Minor Surgery Area Ward Wash Room and Water
.4 5 6	1 - 1 2 4 - 5 - 1. 1 - 1 1 2 - 1 - 1. 1 - 1 1 0 - 1 - 1.	Closet Utility Room Ward Quiet Room Wash Room and
7 8	1 - 1 0 8 - 3 - 1. 1 - 1 0 8 - 1 - 1.	Water Closet Quiet Room Passage



USS PLYMOUTH ROCK


LSD-29

# TRIAGE AREA

LOCATION: 02 Level aft

FLOOR PLAN: Not to scale

EQUIPMENT: None fixed



### MINOR SURGERY AREA

LOCATION: 1-127-1-Q

NORMAL USE: Treatment room and Pharmacy

FLOOR PLAN: Not to scale.

EQUIPMENT:

1-Treatment table

2-Autoclave


3-Sink

4-Cabinet 5-Counter

6-0<sub>2</sub> cylinder

7-Surgical lights 8-Static conductive

floor covering



### PRIMARY WARD

LOCATION: 1-112-1-L

NORMAL USE: Ward and quarters for corpsmen

FLOOR PLAN: Not to scale

- EQUIPMENT: 1-Refrigerator
- 2-Cabinet
- 3-Desk
- 4-Bunks (2 high)
- 5-Lockers
- 6-Counter
- 7-Sink
- 8-Commode
- 9-Shower
- 10-Urinal
- 11-Water fountain

# QUIET ROOM

<u>LOCATION</u>: 1-108-3-L


NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunk (2 high) 2-Locker

3-Desk-Locker

4-Sink 5-Commode 6-Shower



### MEDICAL ADMINISTRATION


LOCATION: 1-132-1-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-File cabinet

2-Desk

3-Typewriter 4-Counter 5-Laboratory cabinet




### MEDICAL SUPPLY

LOCATION: 3-36-2-A

FLOOR PLAN: Not to scale

EQUIPMENT:
Room contains medical supplies including those to support embarked troops.



LOCATION: 1-127-1-Q (same area as Minor Surgery Room)

FLOOR PLAN: See Minor Surgery Room floor plan

EQUIPMENT:
See Minor Surgery
Room equipment.

LOCATION: 1-44-0-L

FLOOR PLAN: Not to scale


**EQUIPMENT:** 

1-Bunks (3 high)

2-Lockers 3-Sink 4-Table

5-Folding OR table 6-BDS locker

7-Scuttle 8-CRS Table 9-Castle lights



LOCATION: 2-148-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunks (24 total,

3 high)

2-BDS locker


3-Table (CRS)

4-Sink

5-Autoclave mount

6-Scuttle

7-Operating table 8-Castle lights



### COMPLEMENT:

SPECIALTY		RANK	OR	RATE
2100 (GMO) 8405 (Independent 0000 0000 0000 0000	Duty)	LT HMC HM1 HM2 HM3 HN		

Note: Marine embarked troops bring one or more corpsmen. Navy embarked troops do not.

### STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

None necessary, as ship is not assigned a Surgical Team.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None provided.

# INVENTORY OF THE MEDICAL CAPABILITY OF THE USS FORT SNELLING LSD-30

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	Page	No.
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Major Medical Space Overview	2	
Minor Surgery Area	2 3	
Primary Ward	4	
Overflow Ward #1		
Overflow Ward #2	5 6	
Quiet Room	7	
Medical Administration	8	
Medical Supply	8 9	
Battle Dressing Station #1	10	
Battle Dressing Station #2	11	
Battle Dressing Station #3	12	
Complement	13	
Status of Outstanding Shipalts	13	
Size and Location of Area for Breakout of Surgical Block	13	
Stowage Near Helo Pad for Replacement Litters and Blankets		

### USS FORT SNELLING

LSD-30

#### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area		None designated
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	#1 BDS	Includes pharmacy
Primary Ward	Ward	10 beds
Overflow Ward(s)	(2)-Crew berthing	36 beds
Quiet Room	Quiet Room	2 beds
Intensive Care Unit		None
X-Ray		None
Physiotherapy.		None
Pharmacy	Minor Surgery	
Blood Storage		None
Morgue		None
Dental OR		None
Dental X-Ray		None
Laboratory	Laboratory	RoutineTests
Admin. Office	Medical Admin.	2 desks, files
Supply Room	Minor Surg. Room	Separate storeroom
Battle Dressing	Standard	3, including Minor
Stations		Surgery

### CASUALTY FLOW:


(1) Helicopter pad on Ol level to Main Deck by ladder to Minor Surgery Room (#1 BDS).
(2) Boat, in well, by ladder or crane to Main Deck to #1 BDS.

# SIGNIFICANT DEFICIENCIES:

None reported by ship.

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION: 1-132-1-Q 1-127-1-Q	FACILITY: Medical Department Office Pharmacy/Minor Surgery Area
3	1 - 1 2 4 - 3 - L	Ward Wash Room and Water Closet
4	1 - 1 2 4 - 5 - L	Utility Room
5	1 - 1 1 2 - 1 - i.	Ward
6	1-110-1-L	Quiet Room Wash Room and Water Closet
7	1-108-3-1	Quiet Room
8	1-108-1-L	Passage



### MINOR SURGERY AREA

LOCATION: 1-127-1-Q

NORMAL USE: Sick call, treatment room, Pharmacy

FLOOR PLAN:

EQUIPMENT: 1-Safe

2-Desk

3-Examination table

4-OR lights 5-Cabinet

6-Steam autoclave


7-Sink

8-Refrigerator 9-Distiller

10 · Shelves

11-Cabinets

12-Battle lantern



### PRIMARY WARD

LOCATION: 1-112-1-L

NORMAL USE: Ward and quarters for corpsmen

FLOOR PLAN: Not to scale

### EQUIPMENT:

1-Refrigerator

2-Cabinet

3-Desk

4-Bunks (2 high)

5-Lockers

6-Counter

7-Sink

8-Commode

9-Shower

10-Urinal

11-Water fountain


# OVERFLOW WARD #1

LOCATION: 1-84-1-L

NORMAL USE: Crew berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (2 high) total 14




# OVERFLOW WARD #2

LOCATION: 1-52-1-L

NORMAL USE: Crew berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (2 high) total 22



# QUIET ROOM


LOCATION: 1-108-3-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Bunk (2 high)
2-Locker
3-Desk-Loc
4-Sink

5-Commode

6-Shower



# MEDICAL ADMINISTRATION


LOCATION: 1-132-1-Q

FLOOR PLAN: Not to scale

EQUIPMENT:
1-File, 4 drawer
2-File, 3 drawer
3-Desk, 3 drawer
4-Metal card index
5-Desk, typewriter
6-Bookcase, overhead
7-Bookcase 7-Bookcase

8-Sink

9-Towel Dispenser




### MEDICAL SUPPLY

LOCATION: 3-36-2-A

FLOOR PLAN: Not to scale

EQUIPMENT:
Medical supplies including instruments,
drugs and misc. lab
material.



<u>LOCATION</u>: 1-127-1-Q (same area as Minor Surgery Room)

FLOOR PLAN: Not to scale

EQUIPMENT: See Minor Surgery Room equipment

LOCATION: 1-44-0-L

FLOOR PLAN: Not to scale


**EQUIPMENT:** 

1-Cabinet 2-Folding OR table 3-OR lights

4-Sink

5-Water tank

6-Bunks




LOCATION: 2-148-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds

2-Folding OR table 3-Surgical lights 4-Sink

5-Overhead water tank 6-Cabinet



### USS FORT SNELLING

LSD-30

### COMPLEMENT:

SPECIALTY		RANK	OR	RATE	
8405	(Independent	Duty)	НМС		
0000	•	•	HM1		
0000			HM2		
0000			HM3		
0000			HN		

### STATUS OF OUTSTANDING SHIPALTS:

None

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

None necessary, as ship is not assigned a Surgical Team.

# STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None provided.

UNCLASSIFIED

# THE PROPERTY OF THE PROPERTY O

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Minor Surgery Area	3
Primary Ward	4
Quiet Room	5
Medical Administration	6
Medical Supply	7
Battle Dressing Station #1	8
Battle Dressing Station #2	9
Complement	10
Status of Outstanding Shipalts	10
Size and Location of Area for Breakout of Surgical Bloc Stowage Near Helo Pad for Replacement Litters and Blank	

### USS SPIEGEL GROVE

LSD-32

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical support for ship's crew(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	No fixed location	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Treatment Room	Folding table
Primary Ward	Ward	10 beds (2 high)
Overflow Ward(s)	Troop & crew space	
Quiet Room(s)	Troop & crew sp/.ce Quiet Room	2 beds (2 high)
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Physiotherapy Pharmacy		None
Blood Storage		None
Morgue		None
Dental OR		None
Dental X-Ray		None
Laboratory		None
Admin. Office	Medical Admin.	2 desks,1 typewriter
Supply Room		3 rooms
Battle Dressing	1-Same area as	Equipped as standard
Stations	Minor Surgery	BDS (total 2)

### CASUALTY FLOW:

(1) Helicopter pad, down narrow and steep ladder to starboard Main Deck to medical area.


(2) By boat along either side, by crane to Main Deck (starboard) or 01 Deck (port). Ladders are narrow and steep with sharp turns.

### SIGNIFICANT DEFICIENCIES:

Third Battle Dressing Station not yet installed.

### MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION: 1-132-1-Q	FACILITY: Medical Department Office
)	1 - 127 - 1 - 0	Pharmacy/Minor Surgery Area
3	1 - 1 2 4 - 3 - L	Ward Wash Room and Water
		Closet
4	1 - 124 - 5 - L	Utility Room
5	1 - 1 1 2 - 1 - L	Ward
O	1 - 1 1 0 - 1 - L	Quiet Room Wash Room and Water Closet
7	1 - 108 - 3 - L	Quiet Room
8	1 - 108 - 1 - L	Passage



### MINOR SURGERY AREA

LOCATION: 1-127-1-Q

NORMAL USE: Treatment Room

FLOOR PLAN: Not to scale **EQUIPMENT:** 

1-Safe

2-Desk

3-Convection heater

4-Folding OR table 5-Minor Surgery locker(overhead)


6-Autoclave

7-Sink

8-Aft BDS cabinet

9-Overhead shelves

10-Med stor counters



### PRIMARY WARD

LOCATION: 1-112-1-L

NORMAL USE: Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-10 beds (2 high)

2-Locker

3-Refrigerator


4-Desk

5-Drinking fountain

6-Commode 7-Sink 8-Showers

9-Urinal

10-Overhead cabinet



# QUIET ROOM


LOCATION: 1-108-3-L

NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunk (2 high)

2-Locker 3-Desk 4-Sink 5-Commode 6-Shower



### MEDICAL ADMINISTRATION


<u>LOCATION</u>: 1-132-1-Q

FLOOR PLAN: Not to scale

8-Sink

EQUIPMENT:

1-File,4 drawer
2-File,3 drawer
3-Desk,3 drawer
4-Metal card index 5-Desk, typewriter 6-Bookcase, overhead 7-Bookcase



### MEDICAL SUPPLY

LOCATION: 3-36-2-A, 3-50-4-A, 2-14-1-Q


FLOOR PLAN: Not to scale

EQUIPMENT: 1-Battle dressings

2-Safe

3-Hypodermic needles
4-I.V. fluids
5-Oral & exter preps
6-Often used preps
7-First aid kits &

seldom used items



USS SPIEGEL GROVE

LSD-32

# BATTLE DRESSING STATION #1

<u>LOCATION</u>: 1-127-1-Q

FLOOR PLAN:

Same area as the Minor

Surgery Area

**EQUIPMENT:** 

Same equipment as Minor Surgery Area

### BATTLE DRESSING STATION #2

LOCATION: 1-41-0-L

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Beds (3 high)

2-Locker

3-Crew's table

4-Folding OR table 5-BDS locker

6-Sink 7-Water tank (ovhu)



USS SPIEGEL GROVE

LSD-32

### COMPLEMENT:

SPECIALTY	RANK OR RATE
8405	НМС
0000	HM1
0000	HM 2
0000	HM3
0000	HN

### STATUS OF OUTSTANDING SHIPALTS:

Third BDS to be installed on next yard overhaul - January 1972.

# SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

None necessary, as the ship is not assigned a Surgical Team.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS HERMITAGE LSD-34

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Pa</u>	age l	No.
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Major Medical Space Overview	2	
Triage Area	2 3	
Minor Surgery Area	4	
Primary Ward	5	
Overflow Ward #1	6	
Overflow Ward #2	7	
Quiet Room	8 9	
Medical Administration	9	
Medical Supply	10	
Battle Dressing Station #1	11	
Battle Dressing Station #2	12	
Complement	13	
Status of Outstanding Shipalts	13	
Size and Location of Area for Breakout of Surgical Block	13	
Stowage Near Helo Pad for Replacement Litters and Blankets	13	

USS HERMITAGE

LSD-34

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Flight or Well Deck	No fixed equipment
Operating Room(s)		None
Non-Ded OR(s)		
Minor Surgery Room	Pharm. &Main BDS	
Primary Ward	Ward	10 beds
Overflow Ward(s)	Sleeping compartment	51 beds total
Quiet Room(s)	Quiet Room	2 beds
Intensive Care Unit		None
X-Ray		None
Physiotherapy Pharmacy		None
		In #1 BDS
Blood Storage		None
Morgue		None
Dental OR		None
Dental X-Ray		None
Laboratory		None
Admin. Office	Medical Admin.	3 desks,2 typewriters
Supply Room	1 Main, 2 Aux.	
Battle Dressing	Non-Ded OR and	Total 2
Stations	Minor Surgery	

### CASUALTY FLOW:


- (1) Helicopter pad 01 level, steep ladder to Main Deck to nonded. OR/BDS #1.
- (2) Boat in Well Deck, by ladder or crane to Main Deck to BDS #1.

### SIGNIFICANT DEFICIENCIES:

Third Battle Dressing Station not yet installed.

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION: 1-132-1-Q	FACILITY: Medical Department Office
,	1 - 1 2 7 - 1 - Q	Pharmacy/Minor Surgery Area
7	•	Ward Wash Room and Water
.5	1 - 124 - 3 - L	Closet
4	1 - 1 2 4 - 5 - L	Utility Room
5	1 - 1 1 2 - 1 - L	Ward
6	I - 110 - 1 - L	Quiet Room Wash Room and Water Closet
7	1 - 108 - 3 - L	Quiet Room
8	1 - 1 0 8 - 1 - 1.	Passage



USS HERMITAGE

LSD-34

# TRIAGE AREA

LOCATION: Helicopter Flight Deck or Well Deck

FLOOR PLAN: Open Space

EQUIIMENT: None fixed

# MINOR SURCERY AREA

LOCATION: 1-127-1-0

NORMAL USE: Pharmacy and Main Battle Dressing Station

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Safe 2-Desk

3-Convection heator 4-Folding OR table

5-Minor surgery locker(overhead)


6-Autoclave

7-Sink

8-Aft BDS cabinet

9-Overhead shelves

10-Med stor counters



### PRIMARY WARD

LOCATION: 1-112-1-L

NORMAL USE: Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-10 beds (2 high)

2-Locker

3-Refrigerator


4-Desk

5-Drinking fountain 6-Commode

7-Sink

8-Showers

9-Urinal



USS HERMITAGE

LSD-34


### OVERFLOW WARD #1

<u>LOCATION</u>: 1-84-1-1.

NORMAL USE: Sleeping Compartment

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (2 & 3 high) total 30



USS HERMITAGE


### OVERFLOW WARD #2

LOCATION: 1-52-4-L

NORMAL USE: CPO berthing

 $\underline{\text{FLOOR PLAN}}$ : Not to scale

EQUIPMENT: 1-Beds (3 high) total 21



# QUIET ROOM


LOCATION: 1-108-3-L

NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunk (2 high)

2-Locker 3-Desk 4-Sink 5-Commode 6-Shower



LSD-34 USS HERMITAGE

### MEDICAL ADMINISTRATION


LOCATION: 1-132-1-Q

FLOOR PLAN: Not to scale

EQUIPMENT:
1-File, 4 drawer
2-File, 3 drawer
3-Desk, 3 drawer
4-Metal card index 5-Desk, typewriter 6-Bookcase, overhead 7-Bookcase

8-Sink


9-Towel Dispenser




## MEDICAL SUPPLY


LOCATION: 3-36-2-A, 3-50-4-A, 3-22-2-A

FLOOR PLAN: Not to scale





EQUIPMENT: 1-Misc. med supplies 2-Instruments 3-Parenteral fluids



USS HERMITAGE LSD-34

### BATTLE DRESSING STATION #1

LOCATION: 1-127-1-Q (Same as Minor Surgery Area)

FLOOR PLAN: (See Minor Surgery Area)

EQUIPMENT: (See Minor Surgery Area)

### BATTLE DRESSING STATTON #2

LOCATION: 1-41-0-L

NORMAL USE: Sleeping compartment

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Folding OR table

2-Sink 3-Cabinet

4-Electric sterilizer

5-Dressing table 6-Beds (3 high-total

18) 7-Table 8-Lockers



USS HERMITAGE LSD-34

### COMPLEMENT:

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
8452-8405	1 - HMC
0000	1 - HM1
8405	1 - HM2
0000	2 - HM 3

Note: One or more HN's should be assigned for training and indoctrination in independent

duty.

### STATUS OF OUTSTANDING SHIPALTS:

None outstanding.

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

None necessary, as the ship is not assigned a Surgical Team.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None

UNCLASSIFIED

THE DEDICAL SAFABLITY
OF THE

UKGLASSIR

# TABLE OF CONTENTS

<u>Item</u>	age	No.
Tactical Mission	1	
Medical Mission	ī	
Medical Assets	1	
Casualty Flow	ī	
Significant Deficiencies		
Major Medical Space Overview	2	
Triage Area	3	
Dedicated Operating Room	4	
Non-Dedicated Operating Room	5	
Primary Ward	6	
Overflow Ward #1	7	
Overflow Ward #2	1 2 3 4 5 6 7 8 9	
Quiet Room	9	
Laboratory	10	
X-Ray	10	
Pharmacy	10	
Central Supply/Sterilization Room	10	
Morgue	10	
Medical Administration	11	
Medical Supply	12	
Battle Dressing Station #1	13	
Battle Dressing Station #2	14	
Battle Dressing Station #3	15	
Complement	16	
Status of Outstanding Shipalts	16	
Size and Location of Area for Breakout of Surgical Block		
Stowage Near Helo Pad for Replacement Litters and Blanket	s 16	

LSD-37 USS PORTLAND

### TACTICAL MISSION:

See MWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

# MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Mess Area	Also BDS
Operating Room(s) Non-Ded OR(s)	Operating Room Surgical Dressing	Main BDS
Minor Surgery Room		None
Primary Ward Overflow Ward(s)	Ward Troop Area	w/Diet Pantry
Quiet Room(s)	Quiet Room	4 Beds
Intensive Care Unit X-Ray	Portable (15 ma)	Use Ward
Physiotherapy	None (13 ma)	
Pharmacy	Pharmacy	Only stocked items
Blood Storage Morgue	None Chill Box	30 x 8 feet
Dental OR	None	
Dental X-Ray Laboratory	None Routine Clinical	
Admin. Office	Medical Administration	
Supply Room	Storage Non Dod OD	2 Rooms
Battle Dressing Station	Triage, Non-Ded. OR and BDS	Well equipped

### CASUALTY FLOW:

Not determined


### SIGNIFICANT DEFICIENCIES:


Not determined

USS PORTLAND LSD-37

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
I	I - 15I - 1 - L	Ward
2	1 - 1 5 1 - 1 - L	Diet Pantry
3	1 - 1 4 6 - 1 - L	Ward Bath
4	1 - 1 4 6 - 1 - Q	Utility Room
5	I - 141 - 1 - L	Operating Room
b	1 - 1 3 7 - 1 - L	Scrub Room
7	1-133-1-Q	Apparatus Room
8	1 - 133 - 1 - Q	Sterilizer Room
i)	1 - 1 2 7 - 1 - L	Surgical Dressing Room
10	1 - 1 2 4 - 1 - A	X-Ray Dark Room
11	1 - 1 2 4 - 1 - A	Medical Stores
1.2	1 - 1 1 7 - 1 - A	Drying Room
13	1-113-1-L	Pharmacy and Laboratory
14	1 - 109 - 3 - Q	Medical Dept. Office





### TRIAGE AREA


LOCATION: 01-68-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Dressing cabinet & portable sterilizer
2-Treatment table
3-Castle lights
4-Hinged shelf
5-Water heater

6-Sink

7-Water tank (overhead) 8-Mess table area



USS PORTLAND LSD-37

### DEDICATED OPERATING ROOM

LOCATION: 1-141-1-L

FLOOR PLAN: Not to scale


EQUIPMENT: 1-OR table 2-Cabinet

3-Solution basin 4-Instrument & dres-

sing stands
5-X-Ray film illuminator
6-Lights

7-Scrub room 8-Cleaning gear locker

9-Water closet



USS PORTLAND LSD-37


# NON-DEDICATED OPERATING ROOM

LOCATION: 1-127-1-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table 2-Cabinet 3-Sink

4-Dressing cabinet
5-Desk
6-Lights
7-X-Ray film illuminator



USS PORTLAND

LSD-37


# PRIMARY WARD

LOCATION: 1-151-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Orthopedic bed
2-Adjustable bed
3-Fixed bed
4-Locker
5-Fountain
6-Refrigerator
7-Sink & counter
8-Diet pantry
9-Shower
10-Toilet
11-Urinal
12-Sink

13-Utility room




### OVERFLOW WARD #1

LOCATION: 2-166-2-L

NORMAL USE: Troop Berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (3 high) 2-Beds (4 high) 3-Lockers



USS PORTLAND

# OVERFLOW WARD #2


LOCATION: 2-123-2-L

NORMAL USE: Troop Berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (3 high) 2-Beds (4 high) 3-Locker

LSD-37



USS PORTLAND


LSD-37

# QUIET ROOM

<u>LOCATION</u>: 02-105-3-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunk 2-Locker



USS PORTLAND LSD-37

#### LABORATORY

LOCATION: I = III3 - I - I.

CAPABILITY: Routine clinical laboratory. Refrigerator available

tor blood storage is in Ward Diet Pantry. Capacity

is 8 cu. ft.

## MAJOR EQUIPMENT:

1. Binocular microscope

3. Table-top centrifuge4. Storage cabinet 42"x60"x24" 2. Built-in incubator

#### X - RAY

LOCATION: Portable unit

## MAJOR EQUIPMENT:

1. Developing tank

2. Portable dryer

## PHARMACY

LOCATION: 1-113-1-L

CAPABILITY: Very limited - primarily storage and dispensing

prepared drugs.

## MAJOR EQUIPMENT:

Scales 1.

2. Storage cabinet

## CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 1-133-1-Q

Autoclaves by type: Steam and/or Electrical

## MORGUE

LOCATION: 2-52-4-A (chill box 0-33°)

STORAGE CAPACITY: 30' x 8'


USS PORTLAND

# MEDICAL ADMINISTRATION

<u>LOCATION</u>: 1-109-3-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Desk 2-File 3-Sink




USS PORTLAND LSD-37


## MEDICAL SUPPLY

LOCATION: 1-124-1-A & 4-28-1-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Shelves 2-Safe





USS PORTLAND

LSD-37

# BATTLE DRESSING STATION #1

LOCATION: 01-68-2-L (Same as Triage Area)

FLOOR PLAN: (See Triage Area)

EQUIPMENT: See Triage Area

# BATTLE DRESSING STATION #2

1.OCATION: 1-127-1-L (Same as Non-dedicated Operating Room)

FLOOR PLAN: (See Non-dedicated Operating Room)

EQUIPMENT: See Non-dedicated OR

USS PORTLAND LSD-37

## BATTLE DRESSING STATION #3

<u>LOCATION</u>: 2-212-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table

2-Lights 3-100 gallon overhead


water tank

4-Sink

5-Water heater

6-Locker

7-Hinged shelf



## COMPLEMENT:

SPECIALTY	RANK OR RATE
8405	HMCS
8452	HM1
8404	HM 2
0000	HM 3

## STATUS OF OUTSTANDING SHIPALTS:

Ship recently constructed

# SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK

Not designated to receive surgical team.

## STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined

INVENTORY OF
THE MEDICAL CAPABILITY
OF THE
USS PENSACOLA
LSD-38

UNGLASSIFIED

No report has been prepared on this ship which is under construction. Receipt of the needed information at a later date will permit its insertion at that time.

INVENTORY OF
THE MEDICAL CAPABILITY
OF THE
USS CHILTON
LPA-38

UNGLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	Page No.
	1
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Triage Area	2
Operating Room	3
Primary Ward	4
Overflow Ward	5
Quiet Room	6
Dental Operating Room #1	7
Dental Operating Room #2	1 2 3 4 5 6 7 8 9 9
Laboratory	9
X-Ray	9
Pharmacy	9
Central Supply/Sterilization Room	10
Morgue	10
Medical Administration	11
Medical Supply	12
Dental Supply	13
Battle Dressing Station #1	14
Battle Dressing Station #2	15
Battle Dressing Station #3	16
Complement	17
comp z omori c	-,

#### TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION

(1) Medical care for ship's crew

(2) Medical support to other ships
(3) Medical support for embarked non-crew personnel

(4) Casualty receiving/evacuation

# MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Open Deck Area	
Operating Room(s)	Operating Room	
Non-Ded OR(s)		None
Minor Surgery Room		None
Primary Ward	Corpsman Berthing	10 Beds
Overflow Ward(s)	Temp. Officer Berth	30 Beds Total
Quiet Room(s)		4 Beds
Intensive Care Unit		None
X-Ray	Portable & Fixed Unit	
Physiotherapy		None
Pharmacy	Pharmacy	Prepared Drugs
Blood Storage		None
Morgue	Food Storage Space	
Dental OR	Dental OR	Two Rooms
Dental X-Ray	Fixed Unit	In OR #2
Laboratory	Diagnostic Procedures	
Admin. Office	Administration	3 Desks, 3 Files
Supply Room	Medical Supply	Four Storerooms
Battle Dressing Stations	Berthing Spaces	Standard Equipment

## CASUALTY FLOW:

Not capable of receiving casualties via helicopter. Casualties received by boat are screened on the quarter deck area and then distributed to one of three Battle Dressing Stations.

## SIGNIFICANT DEFICIENCIES:

Two Dental Operating Rooms with no dental officer on personnel complement.


## TRIAGE AREA


LOCATION: Debark Points: Blue 5 & 6, Green 9 & 10

FLOOR PLAN: Not to scale

EQUIPMENT: 1-First Aid Boxes

2-Litters






## OPERATING ROOM

LOCATION: Main Medical Space

FLOOR PLAN: Not to scale

- EQUIPMENT: 1-Scanlan-Morris autoclave
- 2-Porcelain scrub sink
- 3-Cambridge VSIII **EKG**
- 4-Sterile instrument cabinet
- 5-FSN 6530-709-9035 operating table 6-Anesthesia machine

- 7-Gomco suction 8-Castle lights 9-Burdick DC defibrillator




# PRIMARY WARD

LOCATION: Main Medical Space

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (10) 2-Linen locker




# OVERFLOW WARD

LOCATION: Forward of Main Medical spaces

NORMAL USE: Temporary Officers Quarters

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunks (30)




USS CHILTON

# QUIET ROOM

LOCATION: Main Medical Space

NORMAL USE: Isolation ward and corpsman berthing

FLOOR PLAN: Not to scale EQUIPMENT: 1-Beds (4) 2-Lockers



USS CHILTON

LPA-38


## DENTAL OPERATING ROOM #1

LOCATION: FR 142 Main Deck

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Cabinet

2-Dental chair 3-Dental unit 4-Sink




## DENTAL OPERATING ROOM #2

LOCATION: FR 142 Main Deck

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Cabinet

2-Sink
3-X-Ray unit
4-Air conditioner
5-Dental unit



#### LABORATORY

LOCATION: Main medical spaces

Not capable of storing blood except in emergency CAPABILITY:

situation. Normal laboratory procedures: RPR slide test, monospot, crossmatch, blood type, urinalysis, CBC, gram stain, urine and throat

cultures.

MAJOR EQUIPMENT:

1-Centrifuge - six place head 2-Microscope - 3 objective 3-Centrifuge - hematocrit

4-Incubator

#### X-RAY

LOCATION: Fixed unit in doctor's office, portable unit in OR.

MAJOR EQUIPMENT:

1-Picker Military Field Unit - (6525-601-3680) Fixed Unit 2-Picker Military Field Unit - (6525-680-0893) Mobile Unit

3-Developer and Fixer Tanks with an Air Dry Unit.

## PHARMACY

LOCATION: Main medical spaces

Prescriptions filled for most antibiotics, analgesics, CAPABILITY:

and other prepared drugs. Few, if any, drugs are com-

pounded in the pharmacy.

MAJOR EQUIPMENT:

1-Mortar and pestle 3-Graduates

2-Pill tile and counter 4-Counter balance scales

## CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: Main medical spaces

Autoclaves by Type: Scanlan-Morris Autoclave

## MORGUE

 $\begin{tabular}{ll} \underline{LOCATION}: & Only in emergency situations - refrigerator decks \\ & are utilized. \end{tabular}$ 

## MEDICAL ADMINISTRATION

LOCATION: Main medical spaces


NORMAL USE: Medical administration

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Desks


2-File Cabinets


3-Bookcase





## MEDICAL SUPPLY

LOCATION: As indicated on sketches










# DENTAL SUPPLY

LOCATION: Dental OR #1

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Shelves 2-X-Ray fixer and developer




# BATTLE DRESSING STATION #1

 $\underline{LC}$  'NTION: Sick Bay Treatment Room

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Cabinet 2-Sink 3-Table 4-OR table

5-Castle lights




# BATTLE DRESSING STATION #2

LOCATION: Aft

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Crew's locker area
2-Operating table
3-Castle lights




## BATTLE DRESSING STATION #3

LOCATION: Forward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Crew's berths 2-Removable berths 3-Portable OR table 4-Castle lights



USS CHILTON

LPA-38

## **COMPLEMENT:**

SPEC	IALTY	RANK	OR	RATE
2100	M.O.	LI	MC	
2100	Ass't M.O.	LT	C MC	
2300	Med. Admin.	LT	`JG	MSC
8452		HM	11	
0000		HM	11	
0000		HM	1CS	
8417		HM	12	
8483		HM	12	
0000		HM	12	
0000		HM	13	
0000		HM	13	
0000		HM	13	
0000		HM	13	
0000		HM	13	
0000		SA	\ or	SN
0000		DI	72	

## STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Operating Room and Treatment Room

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Ship has no helo pad.

UNGLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	age No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1 2 3 4 5 6 7
Significant Deficiencies	1
Major Medical Space Overview	2
Operating Room	3
Operating Room (non-dedicated)	4
Minor Surgery Area	5
Primary Ward	6
Quiet Room #1	7
Quiet Room #2	8 9
Dental Operating Room	
Medical Administration	10
Medical Supply	11
Battle Dressing Station #1	12
Battle Dressing Station #2	13
Battle Dressing Station #3	14
Complement	15
Status of Outstanding Shipalts	15
Size and Location of Breakout Area for Surgical Block	15
Stowage Near Helo Pad for Replacement Litters and Blankets	15

#### TACTICAL MISSION:

Sec NWIP 11

## MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

## MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	None identified	
Operating Room(s)	Major Surgery	
Non-Ded OR(s)	Surgical Dressing Room	
Minor Surgery Room	Battle Dressing Station	
Primary Ward	Ward	24 beds
Overflow Ward(s)	None designated	Use Troop berths
Quiet Room(s)	Quiet Room	2 beds
Intensive Care Unit		None
X-Ray	Portable Unit	
Physiotherapy		None
Pharmacy	Pharmacy & Laboratory	
Blood Storage		None identified
Morgue	None identified	Use Food Storage
Dental OR	Dental OR	
Dental X-Ray	In Dental OR	
Laboratory	Laboratory & Pharmacy	
Admin. Office	Administration	
Supply Room	Medical Supply	Two Storerooms
Battle Dressing Stations	Standard Equipment	Three BDS

## CASUALTY FLOW:

(1) By helo: From helo pad on 01 Deck by elevator to Main Deck


to Sick Bay on Main Deck.
(2) By boat: From boat, by litter hoist port or starboard, to Main Deck to Sick Bay on Main Deck.

#### SIGNIFICANT DEFICIENCIES:

(1) X-ray Room (part of Sterilizer Room) is too small.(2) Complement does not provide an O.R. Technician, who is needed even in peace time.

# MAJOR MEDICAL SPACE OVERVIEW

REFERENCE:	LOCATION:	FACILITY:
1	1-101-2-L	Dental Operating Room
2	1 - 9 <b>5 -</b> 2 - L	Operating Room
3	1 - 92 - 4 - L	Sterilizer Room
4	1 - 9 2 - 2 - L	Apparatus Room
5	1 - 8 5 - 2 - L	Operating Room (Non-Ded.)
6	1-105-2-L	Dental Officers S.R.
7	1 - 9 9 - 2 - L	X-Ray Dark Room
8 9	1-91-2-L	Pharmacy & Bact. Laboratory
9	1-86-2-Q	Clerical Office
10	1-105-1-L	Medical Officers' S.R.
11	1-86-0-L	BDS, Minor Surgery Area
12	1-97-1-L	Quiet Room #1
13	1-97-0-L	İsolation Ward/Quiet Rm #2
14	1-95-0-L &	Wash Room & Water
	1-95-1-L	Closet
15	1-91-1-Q	Diet Pantry
16	1-86-1-Q	Medical Dept. Office
17	1-101-3-L	Ward Wash Room & Water
		Closet
18	1-85-1-L	Ward




## OPERATING ROOM

LOCATION: 1-95-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Operating table
2-Castle lights
3-Cabinet
4-Instrument and
dressing stand
5-Instrument stand
6-Sterilizer




## OPERATING ROOM (non-dedicated)

LOCATION: 1-85-2-L

NORMAL USE: Surgical Dressing Room

FLOOR PLAN: Not to scale EQUIPMENT:
1-Operating table
2-Castle lights
3-Examining chair
4-Instrument and dressing stand 5-Scrub sink

6-Cabinet



# MINOR SURGERY AREA

<u>LOCATION</u>: 1-86-0-L


NORMAL USE: Battle Dressing Station #1

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Stowage 2-Operating table 3-Scrub sink 4-Medical locker

5-Sterilizer

6-Castle lights



# PRIMARY WARD


LOCATION: 1-85-1-L

NORMAL USE: Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bunks (24) 2-Desk

3-Linen locker 4-Clothing locker



USS FRANCIS MARION

LPA-249


# QUIET ROOM #1

LOCATION: 1-97-1-L

NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Bunks (2)
2-Locker
3-Medical locker




# QUIET ROOM #2

<u>LOCATION</u>: 1-97-0-L

NORMAL USE: Isolation Ward

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (4) 2-Locker



# DENTA' OPERATING ROOM

<u>LOCATION</u>: 1-101-2-L

 $\underline{\text{NORMAL USE}}$ : Dental Operating Room


FLOOR PLAN: Not to scale

EQUIPMENT:

1-Ritter Unit

2-Operating chair

3-Sink 4-Desk 5-Cabinet




# MEDICAL ADMINISTRATION

<u>LOCATION</u>: 1-86-2-Q

FLOOR PLAN: Not to scale

EQUIPMENT: 1-File cabinet 2-Desk



## MEDICAL SUPPLY

LOCATION: 4-24-1-A and 6-145-4-A


FLOOR PLAN: Not to scale

EQUIPMENT:

Unknown

Medical Storeroom #1

(4-24-1-A)



USS FRANCIS MARION

LPA-249

BATTLL DRESSING STATION #1

LOCATION: 1-86-0-L (Minor Surgery Area)

FLOOR PLAN: See Minor Surgery Area <u>EQUIPMENT</u>

EQUIPMENT:
See Minor Surgery

Area

# BATTLE DRESSING STATION #2


LOCATION: 2-57-3-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Scrub sink 2-Shelf

3-OR table

4-Castle lights 5-Medical locker



# BATTLE DRESSING STATION #3


LOCATION: 2-197-0-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Medical locker 2-Scrub sink

3-Operating table 4-Shelf

5-Castle lights



## USS FRANCIS MARION

LPA-249

## **COMPLEMENT:**

SPECIALTY	RANK OR RATE
2100 Med. Officer	1 LT
2200 Den. Officer	1 LT
2300 Adm. Officer	1 LTJG
8412 Lab Tech	1 HMC
8452 X-ray Tech	1 IIM1
0000	1 HM1
0000	3 IIM2
0000	6 HM3
0000	1 DT 2

# STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF BREAKOUT AREA FOR SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

# UNCLASSIFIED

INVENTORY OF
THE MEDICAL SAPABILITY
OF THE
USS CHARLESTON
LKA-11

USS CHARLESTON LKA-113

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Major Medical Space Overview	2
Triage Area	4
Operating Room	1 2 4 5 6 7
Minor Surgery Area	6
Primary Ward	7
Quiet Room	
Laboratory	8 9 9 9
X-Ray (Portable)	9
Pharmacy	9
Central Supply/Sterilization Room	9
Medical Administration	10
Medical Supply	11
Battle Dressing Station #1	12
Battle Dressing Station #2	13
Battle Dressing Station #3	14
Complement	15
Status of Outstanding Shipalts	15
Size and Location of Area for Breakout of Surgical Bloc	
Stowage Near Helo Pad for Replacement Litters and Blank	
blowage hear hero rad for Replacement Litters and Diank	CCSIS

#### USS CHARLESTON

LKA-113

#### TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Fork Lift Storage	Adj. to Aft BDS
Operating Room(s)	Major Surgery	
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Routine Sick Care	8 Beds
Overflow Ward(s)		None
Quiet Room(s)	Quiet Room	4 Beds
Intensive Care Unit		None
X-Ray	Portable	50 mg unit
Physiotherapy		None
Pharmacy	Routine Drug Disp.	
Blood Storage		None
Morgue		Refrigerator
Dental OR		None
Dental X-Ray		None
Laboratory	Clinical Laboratory	Routine tests
Admin. Office	Administration	
Supply Room	Medical Supply	One Fore, one Aft
Battle Dressing	Three	Standard equipment
Stations		

#### CASUALTY FLOW:

- (1) By helo, down elevator directly to Triage Area adjacent to Aft BDS.
- (2) By boat, directly to Main BDS or Forward BDS. Access to Forward BDS should be port side only. Starboard access has many sharp turns and narrow passageway.

## SIGNIFICANT DEFICIENCIES:

None reported by ship.

# MAJOR MEDICAL SPACE OVERVIEW


RI-FERENCE:	LOCATION:	FACILITY:
	1 - 70 - 2 - 1,	Sterilizing Room
2 3	1 - 67 <b>-</b> 6 - L	Scrub Room
3	1 - 71 - 2 - 1.	Surgical Dressing Room and Main Battle Dressing Station
4	1 - 67 - 4 - L	Operating Room
5	1 - 75 - 0 - Q	Medical Department Office
()	1 - 7 .1 - 0 - 1.	Pharmacy & Bacteriological Laboratory
7	1 - 67 - 2 - L	X-Ray Dark Room
8	1-67-0-L	Quiet Room
8 9	1 - 75 - 1 - Q	Consultation Room
10	1 - 71 - 1 - L	Medical Records Office
11	1-67-1-L	Quiet Room Bath
12	1 - 71 - 3 - L	Útility Room
13	1 - 67 - 3 - L	Diet Pautry
14	1-71-5-L	Ward Bath
15	1 - 7 5 - 3 - A	Medical Storeroom
16	1 - 74 - 1 - L	Vestibule
17	1 - 67 - 5 - L	Ward
18	5 - 76 - 1 - Q	Conveyor

(See Floor Plan, Page 3)

# MAJOR MEDICAL SPACE OVERVIEW

FLOOR PLAN:

(See Reference, Page 2)




## TRIAGE AREA

LOCATION: Adjacent to Aft BDS

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Port med locker
2-"A" frames
3-Overhead wire for
parenteral fluid
4-Med supplies from
Aft BDS
5-Port X-ray unit
6-Elevator



# OPERATING ROOM

ACATION: 1-67-4-L

LOOR PLAN: Not to scale

EQUIPMENT: 1-Operating table

2-Cabinet

3-Static conductive tile


4-Castle lights 5-Emergency lights 6-Portable X-Ray

storage

7-Dressing stands

8-Sink

9-Shower



## MINOR SURGERY AREA

LOCATION: 1-71-2-L


NORMAL USE: Surgical Dressing Room/Main BDS

FLOOR PLAN: Not to scale EQUIPMI

EQUIPMENT:
1-OR table
2-Sterilizer
3-File cabinet
4-Log desk
5-Medical store

5-Medical stores 6-Scrub sink

7-Antidote locker 8-Instr & dress cab 9-Castle lights 10-Sterilizing room 11-Medical stores




## PRIMARY WARD

LOCATION: 1-67-5-L

NORMAL USE: Routine Sick Care

LOOR PLAN: Not to scale



# QUIET ROOM

LOCATION: 1-67-0-L

NORMAL USE: Quiet Room


FLOOR PLAN: Not to scale

# **EQUIPMENT:**

1-Beds (2 high) 2-Cabinet 3-Commode

4-Shower

5-Sink



USS CHARLESTON LKA-113

#### LABORATORY

LOCATION: 1-71-0-L

Routine laboratory procedures. No blood storage capability beyond immediate needs. CAPABILITY:

MAJOR EQUIPMENT:

5-Biological refrigerator 6-Microscope light 1-Binocular microscope

2-Agglutination rotator 7-Demineralizer

3-Centrifuge

4-Incubator

X-Ray (Portable)

**EQUIPMENT:** 

1-Portable X-Ray unit (50 ma) 2-Film processing tank Size I, Type I

PHARMACY

LOCATION: 1-71-0-L

CAPABILITY: Routine dispensing of drugs

MAJOR EQUIPMENT:

1-Pharmacy scales
2-Mortar & pestle
3-Standard measuring equipment

CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 1-70-2-L

Autoclaves by type:

1-Model 20-36 electric and steam fixed autoclave


USS CHARLESTON LKA-113

# MEDICAL ADMINISTRATION

LOCATION: 1-71-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-File cabinet
16 1/2"x25",4 drwr
2-File cabinet cardex
13 1/2"x25",4 drwr
3-Desk
4-Portable X-Ray
50 ma



# MEDICAL SUPPLY

LOCATION: 3-136-1-A(Aft), 2-11-2-A(Fwd), 1-75-3-A

FLOOR PLAN: Not to scale

**EQUIPMENT:** 

1-Pharmacy and lab

supplies


2-Safe

3-X-Ray and surgical

-13'-

supplies 4-Medicine and fluids

1-75-3-A



USS CHARLESTON LKA-113

# BATTLE DRESSING STATION #1

LOCATION: 1-71-2-L (Same area as Minor Surgery)

FLOOR PLAN: See Minor Surgery EQUIPM


EQUIPMENT: See Minor Surgery USS CHARLESTON LKA-113

# BATTLE DRESSING STATION #2

LOCATION: 1-14-2-L

FLOUR PLAN: Not to scale

EQUIPMENT: 1-OR table 2-Scrub sink 3-Water tank 4-Medical locker 5-Castle lights




# BATTLE DRESSING STATION #3

<u>LOCATION</u>: 1-131-0-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-OR table
2-Scrub sink
3-Water tank
4-Medical locker
5-Castle lights



# USS CHARLESTON

LKA-113

# COMPLEMENT:

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
0000	1 HMC
8412 Clinical Lab Asst	1 HM1
8412 Clinical Lab Asst	1 HM2
8452 X-Ray Technician	1 IIM3
8483 OR Technician	1 HM3

# STATUS OF OUTSTANDING SHIPALTS:

None.

# SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

No. 4 Hold, with elevator access to Main Deck.

## STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Stowage in After Battle Dressing Station.

# UNCLASSIFIED

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS EL PASO LYA-117

# TABLE OF CONTENTS

<u>tem</u>	Page	No.
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Major Medical Space Overview	2	
Triage Area	4	
Operating Room	5	
Minor Surgery Area	1 2 4 5 6 7	
Primary Ward	7	
Quiet Room	8	
Laboratory	8 9 9 9	
X-Ray (Portable)	9	
Cast Room	9	
Pharmacy	9	
Central Supply/Sterilization Room	_	
Medical Administration	10	
Medical Supply	11	
Battle Dressing Station #1	12	
Battle Diessing Station #2	13	
Battle Dressing Station #3	14	
Complement	15	
Status of Outstanding Shipalts	15	
Size and Location of Area for Breakout of Surgical Block	15	
Stowage Near Helo Pad for Replacement Litters and Blanke		

USS EL PASO LKA-117

#### TACTICAL MISSION:

See NWIP 11

## 'HEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

#### MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	Fork Lift Storage	Adj. to Aft BDS
Operating Room(s)	Major Surgery	
Non-Ded OR(s)		None
Minor Surgery Room	Main BDS	
Primary Ward	Routine Sick Care	9 Beds
Overflow Ward(s)		None
Quiet Room(s)	Quiet Room	4 Beds
Intensive Care Unit		None
X-Ray	Portable	50 ma unit
Physiotherapy		None
Pharmacy	Routine Drug Disp.	
Blood Storage		None
Morgue		Refrigerator
Dental OR		None
Dental X-Ray		None
Laboratory	Clinical Laboratory	Routine tests
Admin. Office	Administration	
Supply Room	Medical Supply	
Battle Dressing Stations	Three	Standard equipment

## CASUALTY FLOW:

- (1) By helo, down elevator directly to Triage Area adjacent to Aft BDS.
- (2) By boat, directly to Main BDS or Forward BDS. Access to Forward BDS should be port side only. Starboard access has many sharp turns and narrow passageway.

#### SIGNIFICANT DEFICIENCIES:

Not determined.

USS\_EL\_PASO\_

# MAJOR MEDICAL SPACE CVERVIEW


REFERENCE:	<u>LOCATION:</u> 1-70-2-L	FACILITY: Sterilizing Room
2	1-67-6-1	Scrub Room
3	1 - 71 - 2 - L	Surgical Dressing Room and Main Battle Dressing Station
4	1 - 67 - 4 - L	Operating Room
5	1 - 7 <b>5 -</b> 0 - Q	Medical Department Office
()	1 - 71 - 0 - L	Pharmacy & Bacteriological Laboratory
7	1 - 67 - 2 - L	X-Ray Dark Room
8	1 - 67 - 0 - L	Quiet Room
9	1 - 75 - 1 - Q	Consultation Room
10	1 - 71 - 1 - L	Medical Records Office
11	1 - 67 - 1 - L	Quiet Room Bath
12	1 - 71 - 3 - L	Utility Room
13	1 - 67 - 3 - L	Diet Pantry
14	1 - 71 - 5 - L	Ward Bath
15	1 - 75 - 3 - A	Medical Storeroom
16	1 - 74 - 1 - L	Vestibule
17	1-67-5-L	Ward
18	5 - 76 - 1 - Q	Conveyor

(See Floor Plan, Page 3)

# MAJOR MEDICAL SPACE OVERVIEW

 $HLOOR\ PLAN$ : Not to scale

(See Reference, Page 2)



3

10/70

USS EL PASO LKA-117

## TRIAGE AREA

<u>LOCATION</u>: Adjacent to Aft BDS

FLOOR PLAN: Not to scale


EQUIPMENT:

1-Port med locker 2-"A" frames

3-Overhead wire for parenteral fluid 4-Med supplies from Aft BDS

5-Port X-ray unit

6-Casualty elevator from helo pad



Surgical Team Breakout Area

USS EL PASO LKA-117

## OPERATING ROOM

LOCATION: 1-67-4-L

FLOOR PLAN: Not to scale

## **EQUIPMENT:**

1-Operating table

2-Cabinet

3-Static conductive tile

4-Castle lights

5-Emergency lights 6-Portable X-Ray


storage

7-Dressing stands

8-Sink

9-Shower

10-Toilet



USS EL PASO

# MINOR SURGERY AREA


LOCATION: 1-71-2-L

NORMAL USE: Surgical Dressing Room/Main BDS

FLOOR PLAN: Not to scale

EQUIPMENT:
1-OR table
2-Sterilizer
3-File cabinet
4-Log desk
5-Medical stores
6-Scrub sink
7-Antidote locker
8-Instr & dress cab
9-Castle lights


10-Sterilizing room



### PRIMARY WARD

LOCATION: 1-67-5-L

NORMAL USE: Routine Sick Care



### QUIET ROOM

LOCATION: 1-67-0-1.

NORMAL USE: Quiet Room

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Beds (2 high) 2-Cabinet

3-Commode

4-Shower

5-Sink

6-Utensil rack



USS EL PASO LKA-117

### LABORATORY

LOCATION: 1-71-0-L

Routine laboratory procedures. No blood storage capability beyond immediate needs.

MAJOR EQUIPMENT.

Binocular microscope 2. Agglutination Rotator

3. Centrifuge

Incubator

5. Biological refrigerator

6. Microscope light 7. Demineralizer

Hematocrit centrifuge

### X-RAY (Portable)

**EQUIPMENT:** 

Portable X-Ray unit (50 ma)

Film processing tank Size 1, Type I

### CAST ROOM

LOCATION: None designated

CAPABILITY: Long leg casts, walking, short leg casts, long and

short arm casts, finger splints, no pulp traction.

MAJOR EQUIPMENT:

Three and six inch fast setting plaster

Cast cutter

### PHARMACY

LOCATION: 1-71-0-L

CAPABILITY: Routine dispensing of drugs

MAJOR EQUIPMENT:

1. Pharmacy scales

### CENTRAL SUPPLY/STERILIZATION ROOM

LOCATION: 1-70-2-L

Autoclaves by type:

1 - Model 20-36 electric and steam fixed autoclave (35-75 psi)

### MEDICAL ADMINISTRATION


LOCATION: 1-71-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-File cabinet
16 1/2"x25",4 drwr
2-File cabinet cardex
13 1/2"x25",4 drwr

3-Desk

4-Portable X-Ray 50ma




### MEDICAL SUPPLY

LOCATION: 1-73-2-A and 1-75-3-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Bin 2-Locker



USS EL PASO LKA-117

### BATTLE DRESSING STATION #1

LOCATION: 1-71-2-L (Same area as Minor Surgery)

FLOOR PLAN: See Minor Surgery <u>EQUIPMENT</u>:


EQUIPMENT: See Minor Surgery USS EL PASO LKA-117

### BATTLE DRESSING STATION #2

<u>LOCATION</u>: 1-14-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table 2-Scrub sink 3-Water tank 4-Medical locker 5-Castle lights




### BATTLE DRESSING STATION #3

LOCATION: 1-131-0-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table 2-Scrub sink 3-Water tank 4-Medical locker 5-Castle lights



USS EL PASO LKA-117

### COMPLEMENT:

SPECIALTY	RANK OR RATE
2100 Med Officer	LT
0000	1 HMC
8412 Clinical Lab Asst	1 HM2
8452 X-Ray Technician	1 HM3
8483 OR Technician	1 HM3

### STATUS OF OUTSTANDING SHIPALTS:

Not determined

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

No. 4 Hold, with elevator access to Main Deck.

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Stowage in After Battle Dressing Station.

A UNCLASSIFIED

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS TERRESONIE PARISH LST-1158

### TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Medical Supply	3
Battle Dressing Station #1	4
Battle Dressing Station #2	5
Battle Dressing Station #3	6
Complement	7
Status of Outstanding Shipalts	7
Size and Location of Area for Breakout of Surgical Block	7
Stowage Near Helo Pad for Replacement Litters and Blankets	s 7

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation (according to questionnaire reply).

### MEDICAL ASSETS

Assets	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Main Medical Space	Main BDS
Primary Ward		None
Overflow Ward(s)	None Designated	Use Troop berths
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Main Medical Space	Routine drugs
Blood Storage		None
Morgue	None Designated	Use Food Storage
Dental OR		None
Dental X-Ray		None
Laboratory	Main Medical Space	Routine Tests
Admin. Office	Main Medical Space	1 File, 1 Desk
Supply Room	Medical Supply	
Battle Dressing Stations	Standard Equipment	Three BDS

### CASUALTY FLOW:

- (1) By helicopter to landing pad, through narrow hatch down one ladder to second deck through narrow passageway to Sick Bay; or from helo pad down through cargo hatch to Tank Deck, then via casualty hoist to Sick Bay.
- (2) By boat, via rope sling up over the side, then same route as above.

### SIGNIFICANT DEFICIENCIES:

None reported by ship's personnel.

### MINOR SURGERY AREA

LOCATION: 2-45-2-L

NORMAL USE: Sick Bay/Main Battle Dressing Station

FLOOR PLAN: Not to scale EQUIPMENT:

1-Refrigerator

2-Sink


3-Medicine cabinet/
 medical records
4-Treatment table
5-Castle lights

6-Desk

7-Cabinets

8-Autoclave

9-Instrument sterilizer




### MEDICAL SUPPLY

LOCATION: 3-17-4-A

FLOOR PLAN:

EQUIPMENT: 1-Shelves 2-Cabinet

Medical storeroom for parenteral fluids, dressings and bandages, surgical instruments, tablets, equipment.



USS TERREBONNE PARISH LST-1156

### BATTLE DRESSING STATION #1

LOCATION: 2-45-2-L

FLOOR PLAN: Same as Minor Surgery

EQUIPMENT:
Same as Minor
Surgery


### BATTLE DRESSING STATION #2

LOCATION: 2-47-0-L (Crew's Lounge)

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Coke machine
2-Mess tables
3-Battle dressing

locker



### BATTLE DRESSING STATION #3


LOCATION: 2-18-4-L

FLOOR PLAN: Not to scale

Storage for portable Battle Dressing Station equipment and supplies outside forward head on port side.

### EQUIPMENT:

- 1-Portable operating table
- 2-Stowed OR lights (4)
- 3-Battle dressing supply locker
- 4-Sinks
- 5-Commodes (6) 6-Urinals (2)



USS TERREBONNE PARISH

LST-1156

COMPLEMENT:

SPECIALTY

RANK OR RATE

8404 Field Med. Tech.

HM1

STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Tank Deck, as required, and Crew's Lounge (BDS #2).

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Sail Locker.

# UNCLASSIFIED

### USS WALWORTH COUNTY

### TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Battle Dressing Station #1	3
Battle Dressing Station #2	4
Battle Dressing Station #3	5
Medical Supply	6
Complement	7
Status of Outstanding Shipalts	7
Size and Location of Area for Breakout of Surgical Block	7
Stowage Near Helo Pad for Replacement Litters and Blanket	s 7

### USS WALWORTH COUNTY

LST-1164

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Main Medical Space	Main BDS
Primary Ward		None
Overflow Ward(s)	None Designated	Use Troop berths
Quiet Room(s)		None
Intensive Care Unit		None
X-Re,		None
Physiotherapy		None
Pharmacy	Main Medical Space	Routine Drugs
Blood Storage		None
Morgue	None Designated	Use Food Storage
Dental OR		None
Dental X-Ray		None
Laboratory	Main Medical Space	Routine Tests
Admin. Office	Main Medical Space	1 File, 1 Desk
Supply Room	Medical Supply	
Battle Dressing Stations	Standard Equipment	Three BDS

### CASUALTY FLOW:

- (1) By helicopter to landing pad, through narrow hatch, down one ladder to second deck, through narrow passageway to Sick Bay; or from helo pad through cargo hatch to tank deck, then to Sick Bay via hoist.
- (2) By boat via rope sling up over the side, then same route as above.

### SIGNIFICANT DEFICIENCIES:

None reported

### MINOR SURGERY AREA

LOCATION: 2-45-2-L

NORMAL USE: Sick Bay/Main BDS

FLOOR PLAN:

# 7 1 2 6 20'

### EQUIPMENT:

- 1-Refrigerator
- 2-Sink
- 3-Medicine cabinet/
   medical records
- 4-Treatment table
- 5-Castle lights
- 6-Desk
- 7-Cabinets
- 8-Autoclave

USS WALWORTH COUNTY

LST-1164

### BATTLE DRESSING STATION #1

LOCATION: 2-45-2-L

FLOOR PLAN: Same as Minor Surgery Area <u>EQU</u>

EQUIPMENT:
Same as Minor
Surgery Area


### BATTLE DRESSING STATION #2

LOCATION: 2-48-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Operating table
2-Castle lights
3-Medical supply
chest

4-Water tank 5-Scrub sink




### BATTLE DRESSING STATION #3

LOCATION: 2-18-4-L

### FLOOR PLAN:

Storage for portable Battle Dressing Station equipment and supplies outside forward head on port side.

- EQUIPMENT:
  1-Portable operating table
- 2-Stowed OR lights(4)
  3-Battle dressing
  supply locker
- 4-Sinks
- 5-Commodes
- 6-Urinals




### MEDICAL SUPPLY

LOCATION: 3-17-4-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Shelves 2-Cabinet

Medical storeroom for parenteral fluids, dressings and bandages, surgical instruments, tablets, equipment.



USS WALWORTH COUNTY

LST-1164

COMPLEMENT:

SPECIALTY

SPECIALTY

8405 - Independent Duty

RANK OR RAY

HM1 or HM2

RANK OR RATE

STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

# UNCLASSIFIED

THE DEBICAL CORRESPONDENCE.

OF THE DESIGNATION OF

## TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Medical Supply	3
Battle Dressing Station #1	4
Battle Dressing Station #2	5
Battle Dressing Station #3	6
Complement	7
Status of Outstanding Shipalts	7
Size and Location of Area for Breakout of Surgical Block	7
Stowage Near Helo Pad for Replacement Litters and Blanket	s 7

### USS DESOTO COUNTY

LST-1171

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo Pad	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Qtrs.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Sick Bay	
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	
Supply Room	Medical Supply	Three Storerooms
Battle Dressing Stations		Standard Equipment

### CASUALTY FLOW:

(1) From helo pad on Main Deck down one ladder to Sick Bay. If triage is performed in Tank Deck, go directly to Sick Bay via hoist or by ladder to Second Deck.

### SIGNIFICANT DEFICIENCIES:

None reported by ship.

### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

NORMAL USE: Sick Bay

FLOOR PLAN: Not to scale

### **EQUIPMENT:**

1-Supply Cabinet

2-Sink

3-Sterilizer

4-Surgical supply

cabinet

5-Refrigerator 6-Autoclave

7-Desk

8-File cabinet

9-Folding OR table 10-Castle lights

### MEDICAL SUPPLY

LOCATION: 2-17-1-A, 2-48-2-A, 2-49-2-A, 4-21-1-A

### FLOOR PLAN:


Medical Storeroom #1 (2-17-1-A) Parenteral fluids, bulk control supplies, bulk organic supplies

### **EQUIPMENT:**


1-Shelves 2-Safe

3-Mount-out boxes


4-Acid locker




Medical Storeroom #2 (2-48-2-A) Surgical instruments, battle dressings, non-organic supplies



Medical Storeroom #3 (2-49-2-A) Parenteral fluids, oral medications, ointments, etc. Medical Storeroom #4 (4-21-1-A) Mount-out boxes and I.O.L. supplies





USS DESOTO COUNTY LST-1171

### BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery EQUIPMENT:

EQUIPMENT: See Minor Surgery USS DESOTO COUNTY

LST-1171

### BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

FLOOR PLAN:

Uses space within the crew's and troop messing area.
There are no well-defined limits of the battle dressing station.

EQUIPMENT: 1-Folding OR table 2-Medical supply locker

3-Water tank (overhead)

4-Scrub sink 5-Castle lights


### BATTLE DRESSING STATION #3

LOCATION: 2-22-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Med supply locker
2-Folding OR table
3-Scrub sink
4-Water tank

5-Castle lights 6-Bed units (3 high)



USS DESOTO COUNTY

LST-1171

**COMPLEMENT:** 

SPECIALTY
8405 Ind. Duty
RANK OR RATE
HM1

STATUS OF OUTSTANDING SHIPALTS:

Not determined.

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined.

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	ge No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Battle Dressing Station #1	3
Battle Dressing Station #2	4
Battle Dressing Station #3	5
Complement	6
Status of Outstanding Shipalts	6
Size and Location of Area for Breakout of Surgical Block	6
Stowage Near Helo Pad for Replacement Litters and Blankets	6

#### USS SUFFOLK COUNTY

LST-1173

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo Pad	
Operating Room(s) Non-Ded OR(s)		None None
Minor Surgery Room Primary Ward	Sick Bay/Main BDS	None
Overflow Ward(s) Quiet Room(s)	Troop Officer Qtrs.	None
Intensive Care Unit X-Ray		None None
Physiotherapy Pharmacy	Sick Bay	None
Blood Storage		None
Morgue Dental OR	Refrigerator	None
Laboratory Admin. Office	Sick Bay Sick Bay	Routine Tests
Supply Room Battle Dressing	Sick Bay	
Stations		Standard Equipment

#### CASUALTY FLOW:

(1) From helo pad on Main Deck down one ladder to Sick Bay. If triage is performed in Tank Deck, go directly to Sick Bay via hoist or by ladder to Second Deck.

#### SIGNIFICANT DEFICIENCIES:

(1) Portable X-Ray unit and portable laboratory would increase capability and aid Surgical Team greatly when embarked.


(2) Medical storage capacity is inadequate.

#### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

NORMAL USE: Sick Bay

FLOOR PLAN: Not to scale



#### EQUIPMENT:

1-Supply cabinet 2-Sink

3-Sterilizer
4-Surgical supply

cabinet

5-Refrigerator 6-Autoclave

7-Desk

8-File cabinet

9-Folding OR table

10-Castle lights

USS SUFFOLK COUNTY

LST-1173

## BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery <u>EQUIPMENT</u>:

EQUIPMENT: See Minor Surgery

#### BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

FLOOR PLAN:

Uses space within the crew's and troop messing area.
There are no well-defined limits of the battle

dressing station.

EQUIPMENT:

1-Folding OR table 2-Medical supply

locker

3-Water tank (over-

head)

4-Scrub sink 5-Castle lights


#### BATTLE DRESSING STATION #3

LOCATION: 2-22-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Med supply locker
2-Folding OR table
3-Scrub sink

4-Water tank
5-Castle lights
6-Bed units (3 high)



USS SUFFOLK COUNTY

LST-1173

**COMPLEMENT:** 

SPECIALTY

RANK OR RATE

8405 - Independent Duty

HM1

STATUS OF OUTSTANDING SHIPALTS:

Not determined

SIZE AND LOCATION OF BREAKOUT AREA FOR SURGICAL BLOCK:

Not determined

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS GRANT COUNTY LST-1174 4

1

# TABLE OF CONTENTS

<u>Item</u>	Page 1	No.
Tactical Mission	1	
Medical Mission	1	
Medical Assets	1	
Casualty Flow	1	
Significant Deficiencies	1	
Minor Surgery Area	1	
Rattle Dressing Station #1	2	
Battle Dressing Station #1	3	
Battle Dressing Station #2	4	
Battle Dressing Station #3	5	
Complement	6	
Status of Outstanding Shipalts	6	
Size and Location of Area for Breakout of Surgical Block	6	
Stowage Near Helo Pad for Replacement Litters and Blankets	s 6	

#### USS GRANT COUNTY

LST-1174

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

## MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)	Tunk beek	None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Qtrs.	
Quiet Room(s)		None
Intensive Care Unit	None	None
X-Ray		None
Physiotherapy.	C'-l- P-	None
Pharmacy	Sick Bay	Routine Drugs
Blood Storage	Dofo:	None
Morgue Dental OR	Refrigerator	None
Dental X-Ray		None None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	Routine lests
Supply Room	Sick Bay	
Battle Dressing	JICK Day	Standard equipment
Stations		Scandard equipment

#### CASUALTY FLOW:

(1) From helo pad on main deck down one ladder to Sick Bay(2) Casualties in tank deck can be lifted directly to Sick Bay via hoist.

#### SIGNIFICANT DEFICIENCIES:

(1) Filing capacity is inadequate.

#### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:

1-Supply cabinet 2-Sink

3-Sterilizer


4-Supply cabinet 5-Refrigerator 6-Autoclave

7-Desk

8-File cabinet

9-OR table

10-Castle lights



USS GRANT COUNTY LST-1174

#### BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-L (Same area as Minor Surgery)

FLOOR PLAN: See Minor Surgery EQUIPMENT:

EQUIPMENT: See Minor Surgery

LST-1174

#### BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

Uses space within the crew's FLOOR PLAN:

and troop messing area.
There are no well-defined limits of the Battle Dressing Station.

EQUIPMENT: 1-Folding OR table 2-Medical supply

locker

3-Water tank (over-

head)

4-Scrub sink 5-Castle lights

#### BATTLE DRESSING STATION #3

LOCATION: 2-22-1-L


FLOOR PLAN: Not to scale

**EQUIPMENT:** 

1-Med supply locker 2-Folding OR table 3-Scrub sink

3-Scrub sink 4-Water tank 5-Castle ligh

5-Castle lights 6-Bed units (3 high)



USS GRANT COUNTY

LST-1174

COMPLEMENT:

SPECIALTY

RANK OR RATE

8405

HM1

0000

SN

STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Tank deck, as required.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Sail Locker.

# AVENTORY OF THE BEDICAL CAPABILITY OF THE HES YORK COUNTY LET-1178

UNCLASSIFIED

# TABLE OF CONTENTS

Tactical Mission  Medical Mission  Medical Assets  Casualty Flow  Significant Deficiencies  Minor Surgery Area  Medical Supply  Battle Dressing Station #1  Battle Dressing Station #2  Battle Dressing Station #3  Complement  Status of Outstanding Shipalts  Size and Location of Area for Breakout of Surgical Block  Stowage Near Helo Pad for Replacement Litters and Blankets	<u>Item</u>	Page No.	_
Medical Assets Casualty Flow Significant Deficiencies Minor Surgery Area Medical Supply Battle Dressing Station #1 Battle Dressing Station #2 Battle Dressing Station #3 Complement Status of Outstanding Shipalts Size and Location of Area for Breakout of Surgical Block 7	Tactical Mission	1	
Casualty Flow Significant Deficiencies Minor Surgery Area Medical Supply Battle Dressing Station #1 Battle Dressing Station #2 Battle Dressing Station #3 Complement Status of Outstanding Shipalts Size and Location of Area for Breakout of Surgical Block 7	Medical Mission	1	
Significant Deficiencies  Minor Surgery Area  Medical Supply  Battle Dressing Station #1  Battle Dressing Station #2  Battle Dressing Station #3  Complement  Status of Outstanding Shipalts  Size and Location of Area for Breakout of Surgical Block  7	Medical Assets	1	
Minor Surgery Area  Medical Supply  Battle Dressing Station #1  Battle Dressing Station #2  Battle Dressing Station #3  Complement  Status of Outstanding Shipalts  Size and Location of Area for Breakout of Surgical Block  7	Casualty Flow	1	
Medical Supply Battle Dressing Station #1 Battle Dressing Station #2 Battle Dressing Station #3 Complement Status of Outstanding Shipalts Size and Location of Area for Breakout of Surgical Block 7	Significant Deficiencies	1	
Battle Dressing Station #1  Battle Dressing Station #2  Battle Dressing Station #3  Complement  Status of Outstanding Shipalts  Size and Location of Area for Breakout of Surgical Block  7	Minor Surgery Area	2	
Battle Dressing Station #2  Battle Dressing Station #3  Complement  Status of Outstanding Shipalts  Size and Location of Area for Breakout of Surgical Block  7	Medical Supply	3	
Battle Dressing Station #3 6 Complement 7 Status of Outstanding Shipalts 7 Size and Location of Area for Breakout of Surgical Block 7	Battle Dressing Station #1	4	
Battle Dressing Station #3 6 Complement 7 Status of Outstanding Shipalts 7 Size and Location of Area for Breakout of Surgical Block 7	Battle Dressing Station #2	5	
Status of Outstanding Shipalts 7 Size and Location of Area for Breakout of Surgical Block 7		6	
Size and Location of Area for Breakout of Surgical Block 7	Complement	7	
Size and Location of Area for Breakout of Surgical Block 7	Status of Outstanding Shipalts	7	
		7	
		s 7	

#### USS YORK COUNTY

LST-1175

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo Pad	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Qtrs.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Pnysiotnerapy		None
Pharmacy	Sick Bay	
Blood Storage	24-30 pints	Emergency only
Morgue	Refrigerator	
Dental OR		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	1 File, 1 Desk
Supply Room		Three storerooms
Battle Dressing Stations		Standard Equipment

#### CASUALTY FLOW:

(1) From helo pad on Main Deck down one ladder to Sick Bay. If triage is performed in Tank Deck, go directly to Sick Bay via hoist or by ladder to Second Deck.

#### SIGNIFICANT DEFICIENCIES:

(1) Portable X-Ray unit and portable laboratory would increase capability and aid Surgical Team greatly when embarked.
(2) Medical storage capacity is inadequate.

### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Supply cabinet

2-Sink

3-Sterilizer

4-Supply cabinet 5-Refrigerator


6-Autoclava

7-Desk

8-File cabinet

9-OR table

10-Castle lights



#### MEDICAL SUPPLY

LOCATION: 2-15-1-L, 2-49-2-A, 4-21 1/2-1-A


FLOOR PLAN:

EQUIPMENT: 1-Locker


2-Bin

3-Safe

Storeroom #1 - IV Fluids & Instruments (2-15-1-L)




Storeroom #2 - Routine Medicines (2-49-2-A)



Storeroom #3 - Emergency Evacuation Material

(4-21 1/2-1-A)



USS YORK COUNTY

LST-1175

#### BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-1 (Same area as Minor Surgery)

FLOOR PLAN: See Minor Surgery EQUIPME

EQUIPMENT: See Minor Surgery USS YORK COUNTY LST-1175

#### BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

FLOOR PLAN:

Uses space within the crew's and troop messing area.
There are no well-defined

limits of the battle dressing station.

EQUIPMENT: 1-Folding OR table 2-Medical supply

locker

3-Water tank (cver

head)

4-Scrub sink 5-Castle lights


#### BATTLE DRESSING STATION #3

LOCATION: 2-22-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Med supply locker
2-Folding OR table
3-Scrub sink
4-Water tank
5-Castle lights
6-Bed units (3 high)

10/70



USS YORK COUNTY

LST-1175

#### COMPLEMENT:

SPECIALTY RANK OR RATING

8405 - Independent Duty
0000 - General Service
Striker

HM1
HM3
Striker

#### STATUS OF OUTSTANDING SHIPALTS:

Not determined

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined

# UNCLASSIFIED

# INVENTORY OF THE MEDICAL CAPABILITY OF THE USS GRAHAM SOUNTY LST-1148

ei ei eichae

# TAB E OF CONTENTS

<u>Item</u>	Page No
Tactical Mission	•
Medical Mission	Ţ
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Cura- was A	1
Minor Surgery Area	2
Battle Dressing Station #1	3
Battle Dressing Station #2	1
Battle Dressing Station #3	4
Medical Supply	5
Complement	6
Status of Outstanding Shipalts	7
Size and Location of American	7
Size and Location of Area for Breakout of Surgical Block	7
Stowage Near Helo Pad for Replacement Litters and Blanket	s 7

#### USS GRAHAM COUNTY

LST-1176

#### TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

#### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo Pad	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Otrs.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Sick Bay	
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	
Supply Room	Medical Supply	Two Supply Rooms
Battle Dressing Stations		Standard Equipment

#### CASUALTY FLOW:

(1) From helo pad on main deck down one ladder to Sick Bay. If triage is performed in tank deck, go directly to Sick Bay via hoist or by ladder to second deck.

#### SIGNIFICANT DEFICIENCIES:


(1) Portable X-Ray unit and portable laboratory would increase capability and aid Surgical Team greatly when embarked.

#### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

NORMAL USE: Sick Bay

FLOOR PLAN: Not to scale



- EQUIPMENT: 1-Supply cabinet
- 2-Sink
- 3-Sterilizer
- 4-Surgical supply
  - cabinet
- 5-Refrigerator
- 6-Autoclave
- 7-Desk
- 8-File cabinet 9-Folding OR table 10-Castle lights

USS GRAHAM COUNTY LST-1176

# BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery EQUIPMENT

EQUIPMENT: See Minor Surgery

## BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

FLOOR PLAN: Uses space within the crew's and troop messing area.
There are no well-defined limits of the battle

dressing station.

EQUIPMENT:

1-Folding OR table 2-Medical supply

locker

3-Water tank (over-

head)

4-Scrub sink 5-Castle lights

#### BATTLE DRESSING STATION #3


LOCATION: 2 - 2 2 - 1 - L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Med supply locker
2-Folding OR table
3-Scrub sink

4-Water tank

5-Castle lights 6-Bed units (3 high)



#### MEDICAL SUPPLY


LOCATION: 4-59-2-A, 2-17-1-A

FLOOR PLAN: Not to scale


EQUIPMENT: 1-Storage bins 2-Cabinet

3-Safe

4-59-2-A



2-17-1-A



USS GRAHAM COUNTY

LST-1176

COMPLEMENT:

SPECIALTY

RANK OR RATE

8405 - Independent Duty

HM1

STATUS OF OUTSTANDING SHIPALTS:

Not determined

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined

UNGLESSIF (ES)

INVENTORY OF THE NEDICAL CAPABILITY OF THE USS LORAIN COUNTY LST-1977

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Battle Dressing Station #1	3
Battle Dressing Station #2	4
Battle Dressing Station #3	5
Complement	6
Status of Outstanding Shipalts	6
Size and Location of Area for Breakout of Surgical Block	6
Stowage Near Helo Pad for Replacement Litters and Blankets	s 6

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel (3) Casualty receiving/evacuation

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo P	ad
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Qtrs.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy Pharmacy		None
Phármacy	Sick Bay	
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	
Supply Room	Sick Bay	
Battle Dressing		Standard Equipment
Stations		

### CASUALTY FLOW:

(1) From helo pad on Main Deck down one ladder to Sick Bay. If triage is performed in Tank Deck, go directly to Sick Bay via hoist or by ladder to Second Deck.

### SIGNIFICANT DEFICIENCIES:

(1) Portable X-Ray unit and portable laboratory would increase capability and aid Surgical Team greatly when embarked.


(2) Medical storage capacity is inadequate.

### MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

NORMAL USE: Sick Bay

FLOOR PLAN: Not to scale



### **EQUIPMENT:**

- 1-Supply cabinet
- 2-Sink
- 3-Sterilizer
- 4-Surgical supply cabinet
- 5-Refrigerator
- 6-Autoclave
- 7-Desk
- 8-File cabinet
- 9-Folding OR table 10-Castle lights

LOCATION: 2-43 1/2-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery

EQUIPMENT: See Minor Surgery

LOCATION: 2-71-2-L

FLOOR PLAN:

Uses space within the crew's and troop messing area.
There are no well-defined limits of the battle

dressing station.

**EQUIPMENT:** 

1-Folding OR table 2-Medical supply locker

3-Water tank (overhead)


4-Scrub sink 5-Castle lights

LOCATION: 2-22-1-L

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Med supply locker 2-Folding OR table 3-Scrub sink

4-Water tank 5-Castle lights 6-Bed units (3 high)



### USS LORAIN COUNTY

LST-1177

### **COMPLEMENT:**

SPECIALTY	RANK OR RATE
0000	IDAC
0000	HMC
8405	HM1
8405	<b>НМ</b> 2

### STATUS OF OUTSTANDING SHIPALTS:

LST-531K Rev. 1 - Convert Troop Officer Stateroom to Isolation Ward - deferred.

### SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Crew and Troop Messing Compartment 2-59-01-L

### STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None

i (ungliagatita).

INVENTORY OF THE MEDICAL CAPABILITY OF THE USS WOOD COUNTY LST-1178

UNCLASSIFIED

# TABLE OF CONTENTS

<u>ltem</u>	Page No.
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Battle Dressing Station #1	3
Battle Dressing Station #2	4
Battle Dressing Station #3	5
Complement	6
Status of Outstanding Shipalts	6
Size and Location of Area for Breakout of Surgical Block	6
Stowage Near Helo Pad for Replacement Litters and Blanket	ts 6

### USS WOOD COUNTY

LST-1178

### TACTICAL MISSION:

See NWIP 11

## MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

# MEDICAL ASSETS:

Assets	Normal Use/Type	Remarks
Triage Area	Tank Deck Fwd/Helo Pad	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay/Main BDS	
Primary Ward		None
Overflow Ward(s)	Troop Officer Qtrs.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy	Sick Bay	
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	
Supply Room	Sick Bay	
Pattle Dressing Stations		Standard Equipment

### CASUALTY FLOW:

(1) From helo pad on Main Deck down one ladder to Sick Bay. If triage is performed in Tank Deck, go directly to Sick Bay via hoist or by ladder to Second Deck.

### SIGNIFICANT DEFICIENCIES:

(1) Portable X-Ray unit and portable laboratory would increase capability and aid Surgical Team greatly when embarked.


(2) Medical storage capacity is inadequate.

# MINOR SURGERY AREA

LOCATION: 2-43 1/2-2-L

NORMAL USE: Sick Bay

FLOOR PLAN: Not to scale



- EQUIPMENT: 1-Supply cabinet 2-Sink
- 3-Sterilizer
- 4-Surgical supply cabinet
- 5-Refrigerator 6-Autoclave
- 7-Desk
- 8-File cabinet
- 9-Folding OR table 10-Castle lights

USS WOOD COUNTY LST-1178

# BATTLE DRESSING STATION #1

LOCATION: 2-43 1/2-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery <u>EQUIPMENT</u>

EQUIPMENT: See Minor Surgery

LST-1178

### USS WOOD COUNTY

### BATTLE DRESSING STATION #2

LOCATION: 2-59-01-L

FLOOR PLAN:

Uses space within the crew's and troop messing area. There are no well-defined limits of the battle dressing station.

EQUIPMENT: 1-Folding OR table 2-Medical supply

locker

3-Water tank (over-


head)

4-Scrub sink 5-Castle lights

LOCATION: 2-22-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:
1-Med supply locker
2-Folding OR table
3-Scrub sink
4-Water tank
5-Castle lights
6-Bed units (3 high)



USS WOOD COUNTY

LST-1178

**COMPLEMENT:** 

SPECIALTY

RANK OR RATE

0000

HM1 SA

Striker

STATUS OF OUTSTANDING SHIPALTS:

Not determined

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Not determined

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

Not determined

INVENTORY OF THE DEDICAL CAPABILITY OF THE USE NEWFORT LOT - 1179

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	ī
Medical Assets	j
Casualty Flow	1
Significant Deficiencies	$\bar{1}$
Minor Surgery Area	2
Overflow Ward	3
Medical Supply	4
Battle Dressing Station #1	5
Battle Dressing Station #2	6
Battle Dressing Station #3	7
Complement	8
Status of Outstanding Shipalts	8
Size and Location of Area for Breakout of Surgical Block	8
Stowage Near Helo Pad for Replacement Litters and Blanket	s 8

USS NEWPORT LST-1179

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSIGN:

(1) Medical care for ship's crew

(2) Medical support for embarked non-crew personnel(3) Casualty receiving /evacuation

### MEDICAL ASSETS.

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay	
Primary Ward	Sick Bay	
Overflow Ward(s)	Berthing Comp.	
Quiet Room(s)	_	None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy		None
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine tests
Admin. Office	Sick Bay	
Supply Room	Medical Storeroom	
Battle Dressing Stations		Standard Equipment

### CASUALTY FLOW:

(1) Boat to stern ramp, tank deck forward to hoist to main medical

(2) Helo pad, forward on port side through hatch and down ladder to main medical space.

(3) Helo pad, to tank deck via cargo hatch, forward to hoist to main medical space.

### SIGNIFICANT DEFICIENCIES:

None suggested by ship's personnel.

USS NEWPORT LST-1179

### MINOR SURGERY AREA

LOCATION: 2-133-2-L

NORMAL USE: Main Medical Space

FLOOR PLAN: EQUIPMENT:


Not to scale 1-Operating table 2-Surgical lights 7-Stowage rack 13-Safe (over deck)

8-Distiller 14-File cabinet

15-Ward bath 3-Sterilizer 9-Dresser

4-Beds (2 high) 5-Basin ring 10-Locker 16-Inst. Sterilizer

11-Sink 17-Hoist 6-Cabinet 12-Refrigerator 18-Curtains 19-Desk



USS NEWPORT LST-1179


### OVERFLOW WARD

LOCATION: 2-152-4-L

NORMAL USE: Berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (2 high) total 10 2-Lockers




USS NEWPORT LST-1179

# MEDICAL SUPPLY

LOCATION: 4 113-1-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Safe 2-Bins



USS NEWPORT LST-1179

# BATTLE DRESSING STATION #1

LOCATION: 2-133-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery Area EQUIPMENT

EQUIPMENT: See Minor Surgery Area

LST-1179 USS NEWPORT

### BATTLE DRESSING STATION #2

LOCATION: 2-195-1-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table

2-Stokes litter stowage 3-Folding shelf 4-Solution basin 5-Scrub sink

6-Lockers

7-Inst. sterilizer 8-Water tank (overhead)



USS NEWPORT LST-1179

### BATTLE DRESSING STATION #3

LOCATION: 2-97-2-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table, ped. type II

2-Sink 3-Locker 4-Shelf 5-Lockers

6-Sterilizer 7-Beds (3 high)

8-Crew water closet and shower



USS NEWPORT

LST-1179

COMPLEMENT:

SPECIALTY

RANK OR RATE

Independent Duty General Service

HM1 HM3

STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Tank deck, as needed.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None provided, but could be set up. Exchange is routine procedure.

INVENTORY OF THE MEDICAL: CAPABILITY OF THE USB SAGNAW LST-1188

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	ige No
Tactical Mission	1
Medical Mission	1
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Overflow Ward	3
Medical Supply	4
Battle Dressing Station #1	5
Battle Dressing Station #2	6
Battle Dressing Station #3	7
Complement	8
Status of Outstanding Shipalts	8
Size and Location of Area for Breakout of Surgical Block	8
Stowage Near Helo Pad for Replacement Litters and Blankets	8

LST-1188 USS SAGINAW

### TACTICAL MISSION:

See NWIP 11

### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

### MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay	
Primary Ward	Sick Bay	
Overflow Ward(s)	Berthing Comp.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy		None
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine tests
Admin. Office	Sick Bay	
Supply Room	Medical Storeroom	<u> </u>
Battle Dressing Stations	2	Standard Equipment

### CASUALTY FLOW:

- (1) Boat to stern ramp, Tank Deck forward to hoist to main medical space.
- (2) Helo pad, forward on port side through hatch and down ladder to main medical space.
- (3) Helo pad, to Tank Deck via cargo hatch, forward to hoist to main medical space.

### SIGNIFICANT DEFICIENCIES:

None determined; ship is under construction.

USS SAGINAW LST-1188

### MINOR SURGERY AREA

LOCATION: 2-133-2-L


NORMAL USE: Main Medical Space

FLOOR PLAN: EQUIPMENT:
Not to scale 1-Operating table
2-Surgical lights
3-Sterilizer 7-Stowage rack 13-Safe (over deck)

14-File cabinet 15-Ward bath 8-Distiller 9-Dresser

16-Inst. Sterilizer 10-Locker

4-Beds (2 high) 5-Basin ring 11-Sink 17-Hoist 12-Refrigerator 18-Curtains 19-Desk 6-Cabinet



USS SAGINAW LST-1188

### OVERFLOW WARD


LOCATION: 2-152-4-L

NORMAL USE: Berthing

FLOOR PLAN: Not to scale EQUIPM

EQUIPMENT: 1-Beds (2 high) total 10

2-Lockers



USS SAGINAW


LST-1188

### MEDICAL SUPPLY

LOCATION: 4-113-1-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Safe 2-Bins



USS SAGINAW LST-1188

# BATTLE DRESSING STATION #1

LOCATION: 2-133-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery Area EQUIPMENT:

EQUIPMENT: See Minor Surgery Area USS\_SAGINAW LST-1188

## BATTLE DRESSING STATION #2

LOCATION: 2-195-1-L

FLOOR PLAN: Not to scale

EQUIPMENT:


1-OR table

2-Stokes litter stowage

3-Folding shelf 4-Solution basin 5-Scrub sink

6-Lockers

7-Inst. sterilizer 8-Water tank (overhead)



USS SAGINAW LST-1188

### BATTLE DRESSING STATION #3

LOCATION: 2-97-2-L

FLOOR PLAN: Not to scale

EQUIPMENT:


I-OR table, ped. type II

2-Sink
3-Locker

4-Shelf 5-Lockers

6-Sterilizer 7-Beds (3 high)

8-Crew water closet and shower



USS SAGINAW LST-1188

COMPLEMENT:

SPECIALTY
Independent Duty
General Service

RANK OR RATE HM L HM3

STATUS OF OUTSTANDING SHIPALTS:

None

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Tank deck, as needed.

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None provided

USS BOULDER

# INVENTORY OF THE MEDICAL CAPABILITY OF THE USS BOULDER LST-1190

UNCLASSIFIED

# TABLE OF CONTENTS

<u>Item</u>	Page No.
Tactical Mission	1
Medical Mission	$\bar{1}$
Medical Assets	1
Casualty Flow	1
Significant Deficiencies	1
Minor Surgery Area	2
Overflow Ward	3
Medical Supply	4
Battle Dressing Station #1	5
Battle Dressing Station #2	6
Battle Dressing Station #3	7
Complement	8
Status of Outstanding Shipalts	8
Size and Location of Area for Breakout of Surgical Block	8
Stowage Near Helo Pad for Replacement Litters and Blanket	s 8

## TACTICAL MISSION:

See NWIP 11

#### MEDICAL MISSION:

(1) Medical care for ship's crew(2) Medical support for embarked non-crew personnel

(3) Casualty receiving/evacuation

## MEDICAL ASSETS:

Asset	Normal Use/Type	Remarks
Triage Area	Tank Deck	
Operating Room(s)		None
Non-Ded OR(s)		None
Minor Surgery Room	Sick Bay	
Primary Ward	Sick Bay	
Overflow Ward(s)	Berthing Comp.	
Quiet Room(s)		None
Intensive Care Unit		None
X-Ray		None
Physiotherapy		None
Pharmacy		None
Blood Storage		None
Morgue	Refrigerator	
Dental OR		None
Dental X-Ray		None
Laboratory	Sick Bay	Routine Tests
Admin. Office	Sick Bay	
Supply Room	Medical Storeroom	
Battle Dressing Stations		Standard Equipment

#### CASUALTY FLOW:

- (1) Boat to stern ramp, Tank Deck forward to hoist to main medical space.
- (2) Helo pad, forward on port side through hatch and down ladder to main medical space.
- (3) Helo pad, to Tank Deck via cargo hatch, forward to hoist to main medical space.

#### SIGNIFICANT DEFICIENCIES:

None determined; ship is under construction.

### MINOR SURGERY AREA


LOCATION: 2-133-2-L

NORMAL USE: Main Medical Space

FLOOR PLAN: EQUIPMENT:

1-Operating table 7-Stowage rack 13-Safe (over deck)
2-Surgical lights 8-Distiller 14-File cabinet
3-Sterilizer 9-Dresser 15-Ward bath
4-Beds (2 high) 10-Locker 16-Inst. Sterilizer

5-Basin ring 11-Sink 17-Hoist 6-Cabinet 12-Refrigerator 18-Curtains 19-Desk



## OVERFLOW WARD


LOCATION: 2-152-4-L

NORMAL USE: Berthing

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Beds (2 high) total 16

2-Lockers




# MEDICAL SUPPLY

LOCATION: 4-113-1-A

FLOOR PLAN: Not to scale

EQUIPMENT: 1-Safe 2-Bins



# BATTLE DRESSING STATION #1

LOCATION: 2-133-2-L (Same as Minor Surgery)

FLOOR PLAN: See Minor Surgery Area EQUIPMENT:

EQUIPMENT: See Minor Surgery Area

# BATTLE DRESSING STATION #2

LOCATION: 2-195-1-L


FLOOR PLAN: Not to scale

EQUIPMENT: 1-OR table

2-Stokes litter stowage 3-Folding shelf 4-Solution basin 5-Scrub sink

6-Lockers

7-Inst. sterilizer 8-Water tank (overhead)



# BATTLE DRESSING STATION #3

LOCATION: 2-97-2-L


FLOOR PLAN: Not to scale

EQUIPMENT:

I-OR table, ped. type II

2-Sink
3-Locker
4-Shelf
5-Lockers
6-Sterilizer

7-Beds (3 high)
8-Crew water closet and shower



RANK OR RATE

**COMPLEMENT:** 

SPECIALTY

Independent Duty
General Service
HM3

STATUS OF OUTSTANDING SHIPALTS:

Nonc

SIZE AND LOCATION OF AREA FOR BREAKOUT OF SURGICAL BLOCK:

Tank deck, as needed

STOWAGE NEAR HELO PAD FOR REPLACEMENT LITTERS AND BLANKETS:

None provided.

#### SECTION III

#### MEDICAL CAPABILITY SUMMARY

### 3.1 Facility Summary

Figure 3-1, Medical Capability Summary, provides a list of the ships of the Amphibious Force, U. S. Atlantic Fleet, which are anticipated to be in active service in the immediate future. Significant medical assets of each ship identified are listed by quantity. Where a facility is primarily designated to fill a lesser medical role but possesses facilities which could be used for a more demanding medical requirement, it is identified to function in the more demanding capacity. Total assets are grouped by type to provide insight into the quantity and quality of facilities available.

#### 3.2 Medical Capability Qualitative Analysis

No qualitative analysis of medical facilities was attempted except to compare the facilities of a modern hospital to those of the ships surveyed. As a result of this comparison, the name given to the hospital medical area signifies its comparative relationship with the modern hospital. Some criteria established for designation of specific facilities were:

# • Operating Room

- a. A limited access area.
- b. Essential equipment and space for the performance of major surgery including as minimum quality:
  - (1) A fixed operating table with 360° access.
  - (2) Static conductive floor covering.
  - (3) Surgical lights.

#### Non-Dedicated Operating Room

A space suitable for use as an operating room, which is normally used for another purpose. It will generally be necessary to add or remove portable equipment to adapt it for use as an operating room.

#### • Minor Surgery Areas

- a. A limited access area.
- b. Essential equipment to perform minor surgery with local anesthesia.

#### Intensive Care Unit

- a. Single (non-stacked) patient beds.
- b. Monitoring equipment.

#### Battle Dressing Stations

Those meeting standard specifications.

#### • Primary Ward

- a. Beds no more than two high with easy access (preferably 360°) and spaced in such a manner that a wheeled litter could be maneuvered within the ward.
- b. Sufficient medical and medical administrative equipment to care for the total number of patients in the ward.

#### Overflow Ward

Crew or troop compartments used as wards.

#### • Quiet Room

A separate ward containing no more than four beds.

# 3.3 Medical Care Quantitative Analysis

Quantitative analysis of the medical care to be provided by each of the ships, or the total ships of the Amphibious Force, Atlantic is beyond the scope of this report. Figure 3-1 does, however, provide some insight into the potential major surgery capability assuming that appropriate ships are augmented with Surgical Teams, Surgical Support Teams and essential supporting personnel of the ship or landing force as appropriate. Ships listed in Figure 3-1 which were not visited or which did not submit questionnaires were assumed to possess a medical capability similar to a sister ship.

# FIGURE 3-1, MEDICAL CAPABILITY SUMMARY

	dies	L	Seg	SURCERY ROOM		BEOS			X-RAT	-	_		BL000		BATTLE	SURGICAL	IIAJOR
TYPE-HULL	EME	PRINARY	-1625A	MINOR	DENTAL	PRIMARY	ROOMIS	FIXEO	PORTABLE	DENTAL	THERAPY	PHARMACY (1)	STORAGE (PINTS)	LABORATORY (2)	DRESSING STATIONS(3)	CAPACITY (4)	Surgical Cases Per Dat
02-201	USS MOUNT WHITMEY	-		-1	~	=	+	1		-	-	-		DIAGNOSTIC	ď.	340	01
LPH-T	USS CUABALCANAL	-	-	-	~	6	"	I-300mo	I-30 ma	-	-	-	002	DIAGNOSTIC	-	300	01
6-KJ	USS CDAM	-	_	-	2	Ð	-	1-100 ma	1-15 ma	-	_	-	260	DIAGNOSTIC	4	3110	10
LPH-12	USS INCHON	1	_		2	#2	•	1-300 mo	1-15 ma	-	-	-	200	DIAGNOSTIC		ONE	01
LP0-1	USS RALEIGH			-	-	15		7	I-15 mo	-		-		ROUTIME	3		
LP0-3	USS LA SALLE	-		-	-	21			1-50 mo	1			91	ROUTHE	3	PARTIAL	\$
LP0-4	USS AUSTIN	-		_	-	2		-	2-15mg	_				ROUTINE	3	PARTIAL	s
LP0-11	USS CORONADO #	-		-	-	2			0	-				DIAGNOSTIC	3	PARTIAL	s
LP0-I3	USS MASHVILLE	_		-	-	22		-	.0.H	_				OLAGNOSTIC		PARTIAL	s
12-051	USS FORT MANDAM			-		٠		-						ROUTINE	2		
120-52	USS SAN MARCOS			-		•								ROUTINE	,		
62-057	USS PLYMOUTH ROCK			_		2	~							II D.	3		
1.50-30	USS FORT SHELLING			_		ē	2	-		-				ROUTINE	3		
75-0S1	USS SPIEGEL GROVE			-		2	2							II.0.	?		
<b>¥</b> €-0\$1	USS HERMITAGE			-		9	~							II.0.	?		
15-051	USS PORTLAND	_	E			-	-	-	I-15 ma	-		-		ROUTINE	3	= 3NO	01
82-051	USS PEKSACOLA #	-	-			6	-	_	I-IS ma			-		ROUTINE	3	ONE	60
LPA-38	US\$ CHILTON	_			~	9	-	1-100 ma	I-15 mo			-		ROUTINE	3	PARTIAL	S
LPA-249	USS FRANCIS MARION #	-	-	-	-	×	9		<b>.</b> .0.	-		-		DIAGNOSTIC	3	3110	01
רנץ-וו	USS CHARLESTON	-		-		6	-	_	1-50 mo			-		DIAGNOSTIC	3	PARTIM	s
LKA-IIT	USS EL PASO	1		-		9	•	-	1-50 mo			ı		OIACHOSTIC	3	PARTIAL	s
LST-IIS6	USS TERREBONNE PARISH			-						-				ROUTINE			:
LST-II64	USS WALMORTH COUNTY			-					-					ROUTINE	3		
LST-1171	USS DESOTO COUNTY			-										ROUTINE	3		
LST-1173	USS SUFFOLK COUNTT			-										ROUTINE	3		
LST-1174	USS GRANT COUNTY			_						_				ROUTINE	3		
LST-IITS	USS YORK COUNTY			1										ROUTHE	3		
LST-1176	USS GRAHAM COUNTY			1										ROUTINE	3		
121-1177	USS LORAIN COUNTY			-										ROUTINE	3		
LST-1178	USS WOOD COUNTY			-										ROUTINE	3		
LST-II?9	USS NEWPONT			1		•								ROUTINE	2		
LST-1188	# AVEIDVS SSO			1		+								ROUTIME			
1.ST-1130	¥ W∃OTROG SSN			-		•								ROUTIME	3		
10	TOTAL CAPABILITY	=	-	82	2	£2	S	3-300mo	22.1 28.1 5 E E	2	-	=	919	9 DIAGNOSTIC 21 ROUYINE	36		105
HOTES: * DATA TA	NOTES: * DATA TAKEN FROM THAT FURNISHED BY SISTER SHIPS OR FROM BOOKLET OF GEWERAL PLAMS	TER SHIP	'S OR FROM	BOOKLET	OF GENER	IL PLANS.											

NOTES: \* OATA TAKEN FROM THAT FURNISHED BY SISTER SHIPS OR FROM BOOKLET OF GENERAL PLANS.

N.D. NOT DETERMINED.

(1) ETHYRE DISPENSING OR COMPOUNDING CAPABILITY.

(2) ETHYRE DISPENSING OR COMPOUNDING CAPABILITY.

(3) RATE SPALE.

(3) MAT ALSO BE INDICATES ABILITY TO PERFORM BLOOD COUNTY, URINALISIS, AND GRAM STAIR. NOT NECESSARILT A SEPARATE SPACE. "CHACKOSTING" NORATES "ROUTING" PLUS BLOOD CHEMISTRY, BACTERIOLOGT, BLOOD GROUPING AND CROSS MATCHING, AND SPIRAL FLUIO AMALYSIS. SEPARATE.

(3) MAT ALSO BE INDICATED UNDER A SURGEAT ROOM.

(4) "ONE" INDICATES FILL FACILITES FOR A SURGEAL TEAM WITH SUPPLY BLOOK (TWO OPERATING ROOMS), "PARTIAL" INDICATES ONE OPERATING ROOM AND PARTIAL FACILITIES FOR A SURGICAL TEAM WITH SUPPLY BLOOK (TWO OPERATING ROOMS). "PARTIAL"

UNCLASSIFIED Sees-th Classification					
	CHT CONTROL D. T. D			_	
Security Cassification of title, body of abstract	ENT CONTROL DATA - R				
SHIP NATING ACTIVITY (Corporate author)	and innexing annutation must be		ECUTATY CLASSIFICATION		
·		1			
Systems Design, Inc.		SP CHOOP	CLASSIFIED		
		l l	N/A		
AEPORT TITLE		<u> </u>			
Medical Capability Survey					
Amphibìous Force, U.S.A	tlantic Fleet, Oc	tober 19	970.		
<del>*************************************</del>	· · · · · · · · · · · · · · · · · · ·				
A DESCRIPTIVE NOTE (Type of report and inclusive da		1 .	1070		
Technical Report for period anthony (First name, middle initial, last name)	od of October thi	rough Dec	cember 19/0.		
Franklin C. Broadwell					
Raymond J. Mataloni					
Francis B. Merkle					
6 REPORT DATE	74. TOTAL NO, C	F PAGES	78. NO. OF REFS	_	
October 1970	406		None		
ES. CONTRACT OR GRANT NO.	94. ORIGINATOR	S REPORT NUM	ARER(S)	_	
N00014-70-C-0284					
b. PROJECT NO.	None	2			
NR-259-084					
<b>c.</b>	this report)	SICT NO. ST (ANY	other numbers that may be uselgned		
d.	AD		·		
10 DISTRIBUTION STATEMENT		<del></del>			
D: 4 11 41					
Distribution of this repo	rt is unlimited.				
II SUPPLEMENTARY NOTES	12. SPONSORING	MILITARY ACT	TIVITY		
None	• • • • • • • • • • • • • • • • • • •		Research (Code 46	3	
None		Bureau of Medicine & Surgery			
	(Code 4	19)			
13 ABSTRACT	•				
The Medical Capability Su	rvey and Inventor	ov of the	o Shine of the		
Amphibious Force, U. S. A					
and graphic form the medi	cal resources of	those sl	hips. The infor-		
and Starting and would	100001000 01	J J.			

mation presented is based upon questionnaires, drawings, and visits to the ships.

DD . FORM .. 1473

UNCLASSIFIED
Security Classification